

# Series C

## Introduction

The Greenpar series C coaxial connectors are bayonet-coupled connectors designed for full interchangeability with those made to U.S. Military Specification MIL-C-39012.

They are available in both 50- and 75-ohm impedance versions, and may be used with an extensive range of coaxial cables including British Uniradio and American RG types.

The 50-ohm range is not intermateable with the 75-ohm range.

## Performance

*VSWR (typical)* : 1.05 up to 4GHz

*Working voltage* : 1000V peak

*Voltage proof* : 2500V peak


*Temperature range* : -55 to +150°C

## Contents

*Page*

### 50- and 75-ohm series C


Plugs	77
Bulkhead jacks and jacks	78
Panel jacks and bulkhead sockets	79
Panel sockets, bulkhead plugs and panel plugs	80
Adaptors	81
Protective caps	82
Assembly instructions	83-87






**Fig. 1. Improved MIL style braid clamp, non captive centre contact**

1. Place clamp nut, flat washer (when provided) and V-groove gasket over cable. Note that groove in gasket is towards free end of cable.
2. Trim outer sheath from cable, to dimension shown.
3. Fit braid clamp over braid so that internal shoulder butts against end of outer sheath.
4. Fold braid back over clamp, avoiding crossed wires. Trim off surplus braid as shown.
5. Trim dielectric to dimension shown, and check conductor length is as specified.
6. Tin centre conductor.
7. Mount contact (male for plugs; female for jacks) over centre conductor to butt against face of dielectric.
8. Hold cable and contact firmly together, and solder.
9. Slide V-groove gasket, flat washer (if applicable) and clamp nut up to braid clamp. Ensure V-groove gasket seats on clamp.
10. Engage clamp nut in body.
11. Holding body and cable rigid, tighten clamp nut to shear V-groove gasket.





**Fig. 2. Improved MIL style braid clamp, non captive centre contact**

1. Place clamp nut, flat washer (when provided) and V-groove gasket over cable. Note that groove in gasket is towards free end of cable.
2. Trim outer sheath from cable, to dimension shown.
3. Fit braid clamp over braid so that internal shoulder butts against end of outer sheath.
4. Fold braid back over clamp, avoiding crossed wires. Trim off surplus braid as shown.
5. Trim dielectric to dimension shown, and check conductor length is as specified.
6. Tin centre conductor.
7. Mount contact over centre conductor to butt against face of dielectric.
8. Hold cable and contact firmly together, and solder.
9. Slide V-groove gasket and clamp nut up to braid clamp.
10. Press sub-assembly into body as far as possible.
11. Engage clamp nut in body.
12. Holding body and cable rigid, tighten clamp nut to shear V-groove gasket.





**Fig. 3. Improved MIL-style braid clamp, captive centre contact**

1. Place clamp nut, flat washer (when provided) and V-groove gasket over cable. Note that groove in gasket is towards free end of cable.
2. Trim outer sheath from cable to dimension shown.
3. Fit braid clamp over braid so that internal shoulder butts against end of outer sheath.
4. Fold braid back over clamp, avoiding crossed wires.
5. Trim off surplus braid as shown.
6. Trim dielectric to dimension shown, and check conductor length is as specified.
7. Tin centre conductor.
8. Slide holding washer and rear insulator over dielectric to butt against braid.
9. Mount contact (male for plugs; female for jacks) over centre conductor with shoulder pressed against rear insulator.
10. Hold cable and contact firmly together, and solder.
11. Slide V-groove gasket, flat washer (when provided) and clamp nut up to braid clamp. Ensure V-groove gasket seats on clamp.
12. Fit front insulator over contact to butt against rear insulator.
13. Press sub-assembly into body as far as possible, and engage clamp nut.
14. Holding body and cable rigid, tighten clamp nut to shear V-groove gasket.







**Fig. 4. Pressure sleeve cable clamp, captive centre contact**

1. Place clamp nut and plain gasket over cable.
2. Trim outer sheath from cable to dimension shown.
3. Fold back braid and insert ferrule to trap braid between outer sheath and ferrule.
4. Trim off surplus braid as shown.
5. Trim dielectric to dimension shown, and check that exposed centre conductor length is as specified.
6. Tin centre conductor.
7. Slide rear insulator over dielectric to butt against ferrule.
8. Mount contact (male for plugs; female for jacks) over centre conductor with shoulder pressed against rear insulator. Hold cable and contact firmly together, and solder.
9. Slide plain gasket and clamp nut up to ferrule, trapping braid.
10. Slide plain gasket and clamp nut up to ferrule, trapping braid.
11. Fit front insulator over contact to butt against rear insulator.
12. Press sub-assembly into body as far as possible, and engage clamp nut.
13. Holding body and cable rigid, tighten clamp nut to compress plain gasket and retain cable.



## PLUGS



Connector outline	Dim. A B	Assy. data Fig.	Greenpar Eng. No. 50 ohm 75 ohm	Cable clamp	Cable groups															
					1	4	6	7	10	12	25	27	30	52	60	62	73	79	107	
<b>PLUGS</b>    		1	25019	—																
		3	25019	A																
		4	25019	C																
		1	27519	—																
		3	27519	A																
		4	27519	C																
		5	25003	—																
		6	25003	A																
		7	25003	C																
		6 or 5	27503	A or —																
		7	27503	C																
<b>ELBOW PLUGS</b>    		2	25013	—																
		3	25013	A																
		4	25013	C																
		2	27513	—																
		3	27513	A																
		4	27513	C																
		6	25020	A																
		7	25020	C																
		6	27520	A																
	7	27520	C																	

## ORDERING INFORMATION

To order, please specify GREENPAR ENGINEERING No., CABLE CLAMP and CABLE GROUP. e.g. GE 27520C12.



# 50 and 75 ohm series C

## JACKS AND BULKHEAD JACKS

Connector outline	Dim. A   B	Assy. data Fig.	Greenpar Eng. No.		Cable clamp	Cable groups															
			50 ohm	75 ohm		1	4	6	7	10	12	25	27	30	52	60	62	73	79	107	
<b>JACKS</b>    		1	25017		—																
		3	25017		A																
		4	25017		C																
		1		27517		—															
		3		27517		A															
		4		27517		C															
		5	25022		—																
		6	25022		A																
		7	25022		C																
		5		27522		—															
		6		27522		A															
		7		27522		C															

### ORDERING INFORMATION


To order, please specify: GREENPAR ENGINEERING No., CABLE CLAMP and CABLE GROUP. e.g. GE 27522C12.

<b>BULKHEAD JACKS</b>					
		5	25070	—	
		6	25070	A	
		7	25070	C	
		6	27570	A	
		7	27570	C	
		6	{ 25071 25071	A	
		7		C	
		6	27571	A	
		7	27571	C	
		1	25031	—	
		3	25031	A	
		4	25031	C	
		3	27531	A	
		4	27531	C	


### ORDERING INFORMATION

To order, please specify GREENPAR ENGINEERING No., CABLE CLAMP and CABLE GROUP. e.g. GE 27531C1.

### PANEL PIERCING








GE 25070 and 27570



GE 25071, 27571, 25031, 27531.

## PANEL JACKS AND BULKHEAD SOCKETS







Connector outline	Dim. A B	Assy. data Fig.	Greenpar Eng. No. 50-ohm 75-ohm	Cable clamp	Cable groups 1 4 6 7 10 12 25 27 30 52 60 62 73 79 107	
<b>PANEL JACKS</b>						
		1	25016	—		
		3	25016	A		
		4	25016	C		
		3	27516	A		
		4	27516	C		
		6	25098	A		
		7	25098	C		
		6	27598	A		
		7	27598	C		
<b>ORDERING INFORMATION</b> To order, please specify GREENPAR ENGINEERING No., CABLE CLAMP, CABLE GROUP and MOUNTING HOLE details, e.g. GE 27598C12H.			<b>MOUNTING DETAILS</b> 		<b>MOUNTING HOLES</b> 4 - 40 UNC - F 3.2 mm. dia. - H 6 - 32 UNC - J	
			Dimension C: rear mounting — 16.1 Dimension D: front mounting — 19.3 or 14.5 (25098 and 27598)			

<b>BULKHEAD SOCKETS</b> 				<b>PANEL PIERCING</b> 
	25008	27508		
	25087	27587		

<b>ORDERING INFORMATION</b> To order, please specify GREENPAR ENGINEERING No., only.
---

# 50 and 75 ohm series C

## PANEL SOCKETS, BULKHEAD PLUGS, PANEL PLUGS


Connector outline	Greenpar Eng. No. 50 ohm 75 ohm	
<b>PANEL SOCKETS</b> 	25040* 25007* 27507*          25025 27525	<b>MOUNTING DETAILS</b>  *Item 25040 has a 5.0mm. hole for conductor; 25007, a 2.3mm. hole for conductor; and 27507, a 1.3mm. hole for conductor.  4 - 40 UNC - F 3.2 mm. dia. - H 6 - 32 UNC - J  Dimension C: rear mounting - 16.1 Dimension D: front mounting - 11.4
<b>BULKHEAD PLUGS</b> 	25086 27586	<b>PANEL PIERCING</b> 
<b>PANEL PLUGS</b> 	25015 27515	<b>MOUNTING DETAILS</b>  4 - 40 UNC - F 3.2 mm. dia. - H 6 - 32 UNC - J
<b>ORDERING INFORMATION</b> To order, please specify GREENPAR ENGINEERING No. and, where relevant, MOUNTING HOLE details. e.g. GE 25025J.		



## ADAPTORS


## PLUG STRAIGHT ADAPTORS

50 ohm – GE 25023 75 ohm – GE 27523




## JACK STRAIGHT ADAPTORS

50 ohm – GE 25024 75 ohm – GE 27524




## T-ADAPTORS

50 ohm – GE 25009 75 ohm – GE 27509




## ELBOW ADAPTORS

50 ohm – GE 25010 75 ohm – GE 27510




## PANEL STRAIGHT ADAPTORS

50 ohm – GE25058 75 ohm – GE27558




## BULKHEAD STRAIGHT ADAPTORS

50 ohm – GE 25012 75 ohm – GE 27512




## MOUNTING DETAILS



## MOUNTING HOLES

4 - 40 UNC – F  
 3.2 mm. dia. – H  
 6 - 32 UNC – J

## PANEL PIERCING




## ORDERING INFORMATION

To order, please specify GREENPAR ENGINEERING No. and, where relevant, MOUNTING HOLE details. e.g. GE27858H.

# 50 and 75 ohm series C


## PROTECTIVE CAPS

### PLUG CAP AND CHAIN GE 20001



Chain length approx. 63mm.

### JACK CAP AND CHAIN GE 20002




Chain length approx. 75mm.

### ORDERING INFORMATION

To order, please specify GREENPAR  
ENGINEERING No. only. e.g. GE 20001.


**Fig. 5. Improved MIL style braid clamp, non captive centre contact**

- |  |  |  |
|--|--|--|
| <ol style="list-style-type: none"> <li>1. Place clamp nut, flat washer and V-groove gasket over cable. Note that groove in gasket is towards free end of cable.</li> <li>2. Trim outer sheath from cable to dimension shown</li> <li>3. Fit braid clamp over braid so that internal shoulder butts against end of outer sheath.</li> <li>4. Fold braid back over clamp, avoiding crossed wires.</li> </ol> | <ol style="list-style-type: none"> <li>5. Trim off surplus braid as shown.</li> <li>6. Trim dielectric to dimension shown, and check conductor length is as specified.</li> <li>7. Tin centre conductor.</li> <li>8. Mount male contact over centre conductor to butt against face of dielectric.</li> <li>9. Hold cable and contact firmly together, and solder.</li> </ol> | <ol style="list-style-type: none"> <li>10. Slide V-groove gasket, flat washer and clamp nut up to braid clamp. Ensure V-groove gasket seats on clamp.</li> <li>11. Press sub-assembly into body as far as is possible, and engage clamp nut.</li> <li>12. Holding body and cable rigid, tighten clamp nut to shear V-groove gasket.</li> </ol> |
|--|--|--|



**Fig. 6. Improved MIL style braid clamp, captive centre contact**


- |  |   |  |
|--|---|--|
| <ol style="list-style-type: none"> <li>1. Place clamp nut, flat washer (when provided) and V-groove gasket over cable. Note that groove in gasket is towards free end of cable.</li> <li>2. Trim outer sheath from cable to dimension shown.</li> <li>3. Fit braid clamp over braid so that internal shoulder butts against end of outer sheath.</li> <li>4. Fold braid back over clamp, avoiding crossed wires.</li> <li>5. Trim off surplus braid as shown.</li> </ol> | <ol style="list-style-type: none"> <li>6. Trim dielectric to dimension shown, and check conductor length is as specified.</li> <li>7. Tin centre conductor.</li> <li>8. Slide clamp bushing over dielectric to butt against braid, and fit rear insulator to butt against bushing.</li> <li>9. Mount contact (male for plugs; female for jacks) over centre conductor with shoulder pressed against rear insulator.</li> <li>10. Hold cable and contact firmly together, and solder.</li> </ol> | <ol style="list-style-type: none"> <li>11. Slide V-groove gasket, flat washer (when provided) and clamp nut up to braid clamp. Ensure V-groove gasket seats on clamp.</li> <li>12. Fit front insulator over contact to butt against rear insulator.</li> <li>13. Press sub-assembly into body as far as is possible, and engage clamp nut.</li> <li>14. Holding body and cable rigid, tighten clamp nut to shear V-groove gasket.</li> </ol> |
|--|---|--|



**Fig. 7. Pressure sleeve cable clamp, captive centre contact**

- |  |   |  |
|--|---|--|
| 1. Place clamp nut and plain gasket over cable.  | 6. Tin centre conductor.  | 11. Fit front insulator over contact to butt against rear insulator.                           |
| 2. Trim outer sheath from cable to dimension shown.  | 7. Slide rear insulator over dielectric to butt against ferrule.  | 12. Press sub-assembly into body as far as is possible, and engage clamp nut.                  |
| 3. Fold back braid and insert ferrule to trap braid between outer sheath and ferrule.                  | 8. Mount contact (male for plugs; female for jacks) over centre conductor with shoulder pressed against rear insulator. | 13. Holding body and cable rigid, tighten clamp nut to compress plain gasket and retain cable. |
| 4. Trim off surplus braid as shown.  | 9. Hold cable and contact firmly together, and solder.  |  |
| 5. Trim dielectric to dimension shown, and check that exposed centre conductor length is as specified. | 10. Slide plain gasket and clamp nut up to ferrule, trapping braid.   |  |

For C73 see Figure 8.



**Fig. 8. Clamp for semi-rigid cable C73.**

- |  |  |   |
|--|--|---|
| 1. Place clamp nut and plain gasket or metal sleeve over outer conductor.                    | 5. Trim dielectric flush with face of ferrule.   | 9. Holding contact and cable tightly together, solder securely.           |
| 2. Trim outer sheath from cable to dimension shown.  | 6. Tin centre conductor.   | 10. Slide gasket or metal sleeve and clamp nut up to ferrule.             |
| 3. Fit ferrule over outer conductor, until conductor butts against internal step of ferrule. | 7. Slide rear insulator over dielectric to butt against ferrule.                           | 11. Press sub-assembly into body as far as possible and engage clamp nut. |
| 4. Solder ferrule in this position to outer conductor.                                       | 8. Place contact onto centre conductor, with collar pressed into recess in rear insulator. | 12. Holding body and cable rigid, tighten clamp nut firmly.               |

