


1. STRIP CABLE TO DIMENSIONS AS SHOWN



2 .SLIDE THE FERRULE OVER THE CABLE JACKET
INSERT THE CABLE CENTER CONDUCTOR INTO
THE CENTER CONTACT. POSITION THE CONTACT
SO IT BUTTS AGAINST THE CABLE DIELECTRIC.
SOLDER OR CRIMP, USING .067 (1.69mm) HEX DIE,
THE CONTACT ONTO THE CABLE ENSURING
THAT EVEN PRESSURE IS APPLIED TO
CONTACT TIP.

[illegible]




APPLICATION SPECIFICATION




LANGUAGE

ENGLISH



3. FLARE BRAID OVER CONNECTOR BODY AND PUSH THE CONTACT/CABLE ASSEMBLY INTO THE REAR CONNECTOR BODY UNTIL IT BUTTS INSIDE THE CONNECTOR BODY. THE BRAID SHOULD BE SPREAD EVENLY AROUND THE CONNECTOR CRIMP ZONE AT THE CONCLUSION OF THIS STEP.

VERIFY DIMENSION SHOWN



4. SLIDE FERRULE ALONG CABLE UNTIL IT BUTTS AGAINST CONNECTOR BODY AND CRIMP USING .213 (5.41mm) HEX DIE.

REVISE ON PC ONLY		TITLE CABLE ASSEMBLY INSTRUCTIONS CA-BNC			
A	Assembly Instructions 89678-9040				
REV	DESCRIPTION	THIS DOCUMENT CONTAINS INFORMATION THAT IS PROPRIETARY TO MOLEX INC. AND SHOULD NOT BE USED WITHOUT WRITTEN PERMISSION			
DESIGN CONTROL	STATUS	WRITTEN BY:	CHECKED BY:	APPROVED BY:	DATE: MO/DAY/YR
URF		TEF	SSS	GMH	05/30/03
DOCUMENT NO. AS-89678-904				FILE NAME: AS-89678-904	SHT NO. 2 of 2