

Assembly instruction Series BNC v5 No.27100

Tools and materials required:

Stanley blade
Scissors, screw driver
Crimp tools (see table below)
Soldering iron 40 Watts
Solder Sn/Pb 60/40 Ø 0,8mm
activated rosin flux

Angle plug for flexible cables

Cable entry : crimped

Connector types: (e.g.)

16 BNC 75 - 2 - 5

16 BNC 75 - 2 - 7

This connector
is supplied
in 3 parts.

Suitable cables :

Centre contact :





soldered

Braid :


crimped

Crimp tool :


cavity 4,95



Slide ferrule A onto cable.
Prepare cable according to diagram.
CAUTION : Do not damage braid,
dielectric and inner conductor
of cable!



Splay out braid and insert cable
in connector body B.
CAUTION : Ensure that braid lies
above the crimp neck.



Slide ferrule A over braid
and crimp as close to connector body B
as possible.
Solder inner conductor to contact.
Screw on cover C.

SUHNER' skilled staff and specialised equipment are available to carry out complete R.F. lead-assembly on your behalf. We mount your connectors on cables at economic prices! Please contact our representative for further details of this service.



HUBER + SUHNER AG CH-9100 HERISAU

Deutscher Text siehe Rückseite