

Assembly instruction Series TNC No. 27216

Tools and materials required :

Stanley blade
Scissors, screw driver
Crimp tool (see table below)
Soldering iron 100 Watts
Solder Sn/Pb 60/40 Ø 0,8mm
activated rosin flux






Right angle plugs for flexible cables

Cable entry : crimped


Connector types : (e.g.)

16 TNC 50-2-7


This connector is supplied in 3 parts	Suitable cables : (e.g.)	K 02252 D		
	Centre contact :	soldered		
	Braid :	cavity A		
	Crimp tool :	1,2 A (red)		



Slide ferrule A onto cable.
Prepare cable according to diagram.
CAUTION : Do not damage braid, dielectric and inner conductor of cable.



Splay out braid and insert cable in connector body B.
CAUTION : Ensure that braid lies above the crimp neck.



Slide ferrule A over braid and crimp as close to connector body B as possible.
Solder inner conductor to contact, press in disc C and screw in cover D.

SUHNER's skilled staff and specialised equipment are available to carry out complete R.F.lead-assembly on your behalf. We mount your connectors on cables at economic prices! Please contact our representative for further details of this service.



HUBER + SUHNER AG CH-9100 HERISAU

Deutscher Text siehe Rückseite