Assembly instruction Series SMB, SMC, SMS^{V3} No. 3039

Tools and materials required: Small soldering iron, 40 Watts/220 to 240° C Solder Sn/Pb 60/40, activated rosin flux Stanley blade, scissors Spanner 6 mm SUHNER 74 Z-0-0-8		Angle plug for flexible cablesCable entry: Pressure sleeveConnector types: (e.g.)16 SMB/C/S 50-1-4c16 SMB/C/S 50-1-5c16 SMB/C/S 50-2-5c16 SMB/C/S 50-2-6c							
					This connector is supplied in 9 parts	Suitable cables e.g.:	RG 178 B/U RG 196 A/U G 01122	RG 174/U RG 188 A/U G 02232-1 bis -10	
						Centre contact: captive	soldered	soldered	
	Braid:	clamped	clamped						
	》 [©] [©] [©] [□]								
	Remove connector body part J using a 6 mm spanner. Slide cable entry nut A, washer B, rubber gasket C and washer D on to cable. Prepare cable according to diagram. Do not damage inner conductor and braid.								
		 Splay out braid and slide neck of pressure sleeve E underneath the braid. Cut off overlapping braid wires. Should this operation cause difficulties, cut cable sheath axially over a length of 3 mm. In some cases, two slots are necessary. 							
		Slide prepared cable end into connector body F until the inner conductor of cable protrudes 3 mm. Secure cable by tightening cable entry nut A. (torque 1Nm)							
		Lightly tin inner conductor of cable and bore hole of contact pin H. Slide insulator G over inner conductor. Heat contact pin H and introduce inner conductor of cable. Remove soldering iron quickly in order to avoid heat damage to cables with PE-dielectric. Surface of contact pin H must remain clean.							
A 0 10 20 30 49	F	Screw together body parts F and J using a 6 mm spanner. (74 Z-0-0-8) (torque 1Nm)							
	1								

SUHNER's skilled staff and specialised equipment are available to carry out complete R.F. lead-assembly on your behalf. We mount your connectors on cables at economic prices! Please contact our representative for further details of this service.

HUBER+SUHNER Ltd. CH-9100 HERISAU

Deutscher Text: siehe Rückseite

ŝ.,