



Assembly instruction

Cable plug, cable jack, bulkhead and panel jack, straight C, J, N


Suitable cables e. g.

RG-6 A/U
RG-222/U


Centre contact: captivated




Slide cable entry nut A, washer B and rubber gasket C onto cable. Remove carefully 8 mm of cable sheath.



Slide braid clamp D over the braid. Fold back braid over clamp D and trim overlapping braid. Remove carefully 5 mm of dielectric.



Slide washer E and insulator F over dielectric. Presolder inner conductor and centre contact soldering bore (200–250 W soldering iron). Push inner conductor into heated centre contact. Remove soldering iron quickly to avoid melting of dielectric.





Slide connector body onto prepared cable. Tighten cable entry nut A using a 11 mm spanner (74 Z-0-0-3). Do not twist the cable.

Angle plug C, J


Suitable cables e. g.

RG-6 A/U
RG-222/U


Centre contact: captivated




Slide cable entry nut A, washer B and rubber gasket C onto cable. Remove carefully 7.5 mm of sheath.



Slide braid clamp D over the braid. Fold back braid over clamp D and trim overlapping braid. Remove carefully 3.5 mm of dielectric.



Slide washer E and insulator F over dielectric. Presolder inner conductor and centre contact soldering bore (200–250 W soldering iron). Push inner conductor into heated centre contact. Remove soldering iron quickly to avoid melting of dielectric.



Slide connector body onto prepared cable. Tighten cable entry nut A using a 11 mm spanner (74 Z-0-0-3). Do not twist the cable.



HUBER + SUHNER Ltd. CH-9100 HERISAU
Switzerland

AA 08.01.97
324/MDC

Series C, J, N
No. 3045