

Assembly instruction

Series SMA

AG 02/21/00
MAP

No. 3068

Tools and materials required :

CAUTION: solder temperature max. 200°C, heat max. 1 min.

Soldering iron 80 to 100 Watts Solder Sn/Pb 60/40

Activated rosin flux, Alcohol, brush, blade (74 Z-0-0-68)

Soft hammer, small press or small bench vice

SR cable stripping tool No. W 157

Tip trimmer No. W 164

Locator tool "M" No. W 14

Shrink tube for:

Multiflex 86 FEP 73 Z-0-0-299

Multiflex 141 FEP 73 Z-0-0-300

Right angle plug for EZ and Multiflex cables

Cable entry : soldered

Connector types : (e.g.)

16 SMA-50-2-3

16 SMA-50-2-43

16 SMA-50-2-53

16 SMA-50-3-3

16 SMA-50-3-43

16 SMA-50-3-53

Cables : (e.g.)



EZ 86 , (.086")

Multiflex 86


EZ 141 , (.141")

Multiflex 141

This connector
is supplied
in 2 parts



Multiflex




Prepare Multiflex cable according to diagram.

Lightly tin 6mm braid.

Use appropriate shrink tube for strain relief (see table above).

EZ




Cut cable end perpendicular to cable axis. Cut back copper jacket / braid using cable stripping tool W 157.

See instruction sheet No. 9144 for detailed description.

The tool must be set for 3mm stripping dimension.


SM / Multiflex




Remove dielectric using a blade.

(for EZ-cables remove dielectric flush with copper jacket)

Form tip of inner conductor to a 90° cone using tip trimmer W 164.




Screw locator tool "M" W 14 to connector body B, fix connector in a small bench vice.



Slide prepared cable into connector body B until inner conductor of cable is flush at point x.

Solder inner conductor to contact pin, slot has to be filled up with solder. Rim y must remain free of solder. Solder connector body B to copper jacket at point z. Promptly swab soldered area with alcohol to cool joint and remove any residual flux.



Position with locator tool "M" W 14 downwards on a solid base.

Place cover A on rear aperture of connector body B.

Carefully drive cover A into connector body B using a soft hammer, a small press or a small bench vice.

Remove locator tool "M" W 14 and check interface dimensions.

UNCONTROLLED COPY WHEN PRINTED

HUBER + SUHNER's skilled staff and specialised equipment are available to carry out complete RF. lead-assembly on your behalf.
We mount your connectors on cables at economic prices! Please contact our representative for further details of this service.



HUBER + SUHNER