




Assembly instruction Series UHF, N J8 No. 3076

Tools and materials required: Stanley blade Scissors, Screwdriver Crimp tool (see table below) Soldering iron 100 Watts Solder Sn/Pb 60/40 $\varnothing$ 0,8 mm activated rosin flux		Angle plug for flexible cable		
		Cable entry: Crimp (inner conductor soldered)		
		Connector types: (e. g.) 16 UHF 0-7-4c 16 N 50-7-30c 16 UHF 0-7-5c 16 N 50-7-31c		
This connector is supplied in 3 parts	Suitable cables: (e. g.)	RG 213/U RG 214/U		
	Centre contact: capt.	soldered		
	Braid:	cavity D		
	Crimp tool:	3 D (violett)		




Type	X	Y	Z
16 UHF	26	17	4
16 N	21	12,5	4


Prepare cable according to diagram.
CAUTION: Do not damage braid, dielectric and inner conductor of cable!



Remove cover from connector body B.
Slide ferrule A onto cable.
Splay out braid by a conical movement of the crimp spigot.
Push spigot of connector body B under braid.
Centre conductor of the cable must slide into the hollow of the contact pin.



Slide ferrule over braid and crimp as close to connector body B as possible.
Solder inner conductor and screw on cover C.



SUHNER's skilled staff and specialised equipment are available to carry out complete R. F. lead-assembly on your behalf.
We mount your connectors on cables at economic prices! Please contact our representative for further details of this service.



HUBER+SUHNER LTD. CH-9100 HERISAU

Deutscher Text: siehe Rückseite