

Assembly instruction

Series BNC

E 6

No. 9030

Tools and materials required:

Stanley blade, scissors

Crimp tool (see table below)

Straight cable connector

Cable entry: SUHNER Full-Crimp

Connector types: (e. g.)

11 BNC 75-6-2c

11 BNC 75-6-4c

This connector is supplied in 3 parts.

Suitable cables e. g.

F+G 1,0/6,4

G 06133-4

Centre contact: capt.

cavity 2

cavity 2

Braid:





cavity 9,75

cavity D


Crimp tool:

2, 9,75


2 D




Slide ferrule A onto cable.
Prepare cable according to diagram.
Do not damage braid and inner conductor of cable.




Push contact pin B over inner conductor of cable to abut cable dielectric and crimp. (Crimp tool cavity 2)



Splay out braid by a conical movement of the crimp spigot.
Push spigot of connector body C under braid until contact pin engages perceptibly.



Slide ferrule A over braid to abut connector body and crimp as close to connector body C as possible.



SUHNER's skilled staff and specialised equipment are available to carry out complete R.F. lead-assembly on your behalf.
We mount your connectors on cables at economic prices! Please contact our representative for further details of this service.



HUBER + SUHNER Ltd. CH-9100 HERISAU

Switzerland

Deutscher Text: siehe Rückseite