

Assembly instruction

Series BNC

E12 **No. 9098**

Tools and materials required:

Stanley blade
Scissors
Crimp tool (see table below)

Straight connectors for flexible cable

Cable entry: SUHNER Full-Crimp

Connector types: (e. g.)

11 BNC 50-4-23
11 BNC 75-4-19c
24 BNC 50-4-8c
24 BNC 75-4-12c

This connector
is supplied
in 4 parts

Suitable cables e. g.:

RG 62 A/U
RG 71 B/U

Centre contact:



cavity 2

Braid:


cavity C

Crimp tool:


2 C (yellow)




Slide ferrule A onto cable.
Prepare cable according to diagram.
CAUTION: Do not damage braid
and inner conductor of cable!




Slide insulator B to abut cable dielectric.
Push contact C over inner conductor of cable
to abut insulator B and crimp.



Splay out braid and insert cable in connector body D.
Ensure that braid lies above the crimp neck.



Slide ferrule A over braid and crimp as close to connector
body D as possible.



SUHNER's skilled staff and specialised equipment are available to carry out complete R.F. lead-assembly on your behalf.
We mount your connectors on cables at economic prices! Please contact our representative for further details of this service.



HUBER + SUHNER Ltd. CH-9100 HERISAU

Switzerland

Deutscher Text: siehe Rückseite