## Assembly instruction Series N

FA No. 9099

Tools and materials required:		Straight connectors for flexible cable		
Stanley blade Scissors Small soldering iron 40 Watts Solder Sn/Pb 60/40 activated rosin flux Spanner 7 mm (74 Z-0-0-38) 8 mm (74 Z-0-0-16) 13 mm (74 Z-0-0-37) Assembly tool for taper sleeve (74 Z-0-3-1)		Cable entry: Screw-type		
		Connector types 11 N-50-3-52	: <b>(e. g.)</b> 11 N-50-3-53	11 N-50-3-54
This connector is supplied in 7 (6) parts	Suitable cables e.g.:	RG 223/U RG 400	RG 400	RG 223/U
	Centre contact:	soldered	soldered	soldered
	Braid:	screwed	screwed	screwed
	Taper sleeve:	78 Z-0-3-4	without	without
		Slide taper sleeve A (supplied with 11 N-50-3-52 only), nut and gasket C onto cable. Prepare cable according to diagram. CAUTION: Do not damage braid!		
		Push braid back and widen it slightly but do not comb it ou Cut back dielectric 1,7 mm perpendicular to cable axis. Lightly tin inner conductor! (RG 400)		
		Taper braid towards center conductor. Position braid clamp D so that its shoulder fits against cable sheath.		
	Slide clamp E un of 0,8 mm. Heat i (approx. 40 W) at Push cable inner	Fold back braid over clamp D and trim overlapping braid. Slide clamp E underneath the braid. Check dimension of 0,8 mm. Heat inner contact E using a soldering iron (approx. 40 W) and flow small amount of solder into bore. Push cable inner conductor into bore, immediately remov soldering iron to prevent melting of the dielectric.		
0	and tighten nut E	Push prepared cable into connector body G and tighten nut B. Do not rotate cable in connector body. Slide taper sleeve (supplied with 11 N-50-3-52 only) over nut B using an assembly tool.		

SUHNER's skilled staff and specialised equipment are available to carry out complete R.F. lead-assembly on your behalf. We mount your connectors on cables at economic prices! Please contact our representative for further details of this service.

HUBER+SUHNER Ltd. CH-9100 HERISAU Switzerland

Deutscher Text: siehe Rückseite