

Assembly instruction

Series BNC G9 No. 9121

Tools and materials required:
Stanley blade, scissors
Crimp tool (see table below)

Straight cable connector

Cable entry: SUHNER Full-Crimp

Connector types. (e. g.)

24 BNC 50-7-3

This connector
is supplied
in 3 parts.

Suitable cables e. g.

RG 213/U

Centre contact: capt.





cavity 3

Braid:


cavity D

Crimp tool:


3 D (violett)




Slide ferrule A onto cable.
Prepare cable according to diagram.
Do not damage braid and inner conductor of cable.




Push contact pin B over inner conductor of cable to abut
cable dielectric and crimp. (Crimp tool cavity 2)



Splay out braid by a conical movement of the crimp spigot.
Push spigot of connector body C under braid.



Slide ferrule A over braid to abut connector body
and crimp as close to connector body C as possible.



SUHNER's skilled staff and specialised equipment are available to carry out complete R.F. lead-assembly on your behalf.
We mount your connectors on cables at economic prices! Please contact our representative for further details of this service.



HUBER + SUHNER Ltd. CH-9100 HERISAU

Switzerland

Deutscher Text: siehe Rückseite