





Tools and materials required:		Straight connector for flexible cable			
Knife or razor blade scissors Crimp tool (see table)		Cable entry: SUHNER Full Crimp			
		Connector types:(e.g.)			
		11 MMCX 50-1-1 21 MMCX 50-1-1 24 MMCX 50-1-1	11 MMCX 50-1-2 21 MMCX 50-1-2 24 MMCX 50-1-2	21 MMCX 50-1-3	11 MMCX-50-1-9
This connector is supplied in 3 parts	Suitable cables:	RG 178 B/U	K 01152-7	MURATA	Gore CXN 2856
	Centre contact:	cavity (1) 0,75			
	Braid:	cavity 2,67			
	Crimp tool (small) (large)	76 Z-0-2-53 76 Z-0-0-26			



	Prepare cable according to diagram. Connector types	L
	...MMCX 50-1-1 /-9	4,8mm
	...MMCX 50-1-2 /-3	3,7mm
	Slide ferrule A over the braid until shoulder abuts the cable sheath. Fold back braid over ferrule A and trim overlapping braid.	
	Prepare cable according to diagram. CAUTION : Do not damage braid, dielectric and inner conductor of cable.	
	Push contact B over inner conductor of cable to abut cable dielectric and crimp.	
	Control dimension Y :	
	Connector types	Y
	...MMCX 50-1-1 /-9	0,7...1,3mm
	...MMCX 50-1-2 /-3	0,9...1,4mm
	Push contact B into the body C.	
	Crimp body C. Make sure that crimping is symmetrical on body C.	
	Types	X
	11 MMCX ... 21 MMCX ...	typ 1,0 mm

SUHNER's skilled staff and specialised equipment are available to carry out complete R.F.lead-assembly on your behalf. We mount your connectors on cables at economic prices! Please contact our representative for further details of this service



HUBER + SUHNER AG CH-9100 HERISAU

Deutscher Text siehe Rückseite