Assembly instruction Series UHF E No. 3075

3D (violett)

Tools and materials required: Stanley blade Scissors Crimp tool (see table below)		Straight connectors for flexible cable Cable entry: SUHNER Full-Crimp			
		This connector is supplied in 3 parts	Suitable cables e.g.:	RG 58 C/U	RG 59 B/U
Centre contact:	cavity 2		cavity 2	cavity 2	cavity 3
Braid:	cavity B		cavity C	cavity D	cavity D ·
					· 1

2B (orange)




Crimp tool:






2D


2C (yellow)




Slide ferrule A onto cable. Prepare cable according to diagram. CAUTION: Do not damage braid and inner conductor of cable!



Push contact B over inner conductor of cable to abut cable dielectric and crimp.



Splay out braid and insert cable in connector body C. Ensure that braid lies above the crimp neck.



Slide ferrule A over braid and crimp as close to connector body C as possible.



SUHNER's skilled staff and specialised equipment are available to carry out complete R. F. lead-assembly on your behalf. We mount your connectors on cables at economic prices! Please contact our representative for further details of this service.



IBER+SUHNER LTD. CH-9100 HERISA