

Tools and materials required:

Stanley blade

Scissors

Crimp tool (see table below)

Straight connectors for flexible cable

Cable entry: SUHNER Full-Crimp

Connector types: (e. g.)

11UHF-0-3-17c

21UHF-0-3-1c

11UHF-0-4-14c

21UHF-0-4-1c

11UHF-0-7-21c

21UHF-0-7-6c

11UHF-0-7-17c

21UHF-0-7-2c

This connector
is supplied
in 3 parts

Suitable cables e. g.:

Centre contact:

Braid:

Crimp tool:

RG 58 C/U

cavity 2

cavity B

2B (orange)

RG 59 B/U

cavity 2

cavity C

2C (yellow)

RG 11 A/U

cavity 2

cavity D





2D

RG 213/U

cavity 3

cavity D


3D (violett)




Slide ferrule A onto cable.

Prepare cable according to diagram.


CAUTION: Do not damage braid and inner conductor of cable!




Push contact B over inner conductor of cable to abut cable dielectric and crimp.



Splay out braid and insert cable in connector body C. Ensure that braid lies above the crimp-neck.



Slide ferrule A over braid and crimp as close to connector body C as possible.



SUHNER's skilled staff and specialised equipment are available to carry out complete R. F. lead-assembly on your behalf. We mount your connectors on cables at economic prices! Please contact our representative for further details of this service.



HUBER+SUHNER LTD.



modular systems

P.O. Box 38-828,

PETONE, Wellington,

New Zealand.

PHONE: (64-4) 5687 277

FAX: (64-4) 5685 161



seite