

NOTE

Make sure that you read these notes from start to finish before attempting any construction of any of the kits.

These notes may contain last minute warnings and/or changes.

CAUTION

When connected to any machine unexpected movements that may be dangerous may occur. To minimise this possibility always turn off your CNC equipment while your computer is booting or not directly involved with controlling your CNC equipment.

INTRODUCTION TO OUR CNC KITS

This series of kits K142A, K142B, K142C and K142D are designed to control machinery via a computer using up to 4 stepper motors.

This system can be used to manufacture one or many items extremely accurately & can be retro fitted to existing milling machines or lathes etc.

BASIC PROCEDURE

Depending on the software chosen, usually an item is drawn, the drawing file is then converted to a Gcode file. The Gcode is then read by your CNC software that in turn controls your machine.

Gcode can also be written with a text editor like Notepad etc.

APPLICATIONS

Some common applications include: milling, turning, engraving, drilling, hot wire foam cutting and animation camera control.

SOFTWARE

You will have to consider to best software for your application. Some of the software available include KCAM, STEPSTER, DANCAD and EMC (Enhanced Machine Controller). Some is freeware, some shareware and some is commercial.

Note:

There are many different types of software that are available, for that reason it is impossible for Oatley Electronics to advise on how to use your software. To use this kit your software should be the STEP & DIRECTION type (this is the most common type). Most software also has configure-able pin connections to match the connections required by the our kits.

DRIVING STEPPER MOTORS

The major problem is as a stepper motor's speed increases the current

drawn by the motor and it's power output slowly drop until it reaches a certain speed (this point varies greatly with motor type) then suddenly the current and power drop to almost nothing, making the motor almost useless at anything other than low speeds. This is caused by insufficient time for each coil's field to break down before the next step. Different systems are often employed to increase the speed of stepper motors like ballast resistors or chopper drives.

BALLAST RESISTORS

To help overcome the lack of performance high wattage resistors are connected in series with the motor coils and a power supply higher than the motor's rated voltage is used.

CHOPPER DRIVES

Chopper drives or PWM (pulse width modulated) drives turn on and off (at high speed) a power supply higher than the motor's rated voltage. This technique is a linear response to a non-linear problem.

CONSTANT CURRENT DRIVES

This type of drive maintains motor current and power by incensing the voltage to the motor as the motor speed rises. Constant current drives force each coil's field to collapse quicker allowing the motor to run much faster.

Our new (K142C) Constant Current Source systems sense the drop in current and increase the voltage to the motor and thus the current and power is maintained with higher speeds.

A common motor we tested gave similar torque at around 300 RPM as at 1 or 2 RPM (this is as FAST as we tested with a 200 step motor). Because of the wide voltage output range of the constant current source we had to re-design our (K142) CNC Stepper Motor Driver Kit to cope.

There are a number of cheap ripoff copies of our K142B kit but most don't allow for the wide voltage range produced by ballast resistor, chopper or constant current system drives.


BASIC KIT DESCRIPTION

K142A is a PC interface that helps to simplify wiring, it also provides 2 relays that are controlled by your PC and can be used to switch just about anything.

CONNECTIONS

Most of the software available uses or can be configured to use the same connections of the printer port. K142A uses the following connections.

PC Pin	Function
2	X axis step
3	X axis direction
4	Y axis step
5	Y axis direction
6	Z axis step
7	Z axis direction
8	C axis step
9	C axis direction
18-25	GND



The "Y" axis is usually a "back and forth" movement, The "X" is usually "left and right" movement and the "C" axis is usually a rotary axis around the "Z" axis but it can also be used as a fourth axis in a foam wing cutter.

The other pins not shown here are often used for limit and home switches and will vary depending on the software you choose to use. In some cases they may not be needed at all or they can be disabled. The power supply in connection is required for the relays and 12VDC output. We recommend 9VAC or 12VDC from a power adaptor or other similar supply. The power supply 12VDC output is used to supply the logic (ICs etc.) of each of the K142B or K142D kits.

The axis outputs supply step and direction signals to each of the K142B or K142D kits. The AUX I/O terminals can generally be connected to things like switches etc. that are placed at the limits of the movement of your CNC machine. This is to stop you machine from moving too far. These connections will vary depending on the software you use, check the documentation that comes with your software..

CAUTION:


Although the relays used in this kit are mains rated we do not recommend that they be connected to mains power as it may be dangerous and result in electric shock.


The relays can be used to switch on or off auxiliary items such as your machine's spindle motor, coolant, hot wire, drill, dust extractor or vacuum cleaner, just about anything you can think off. Relay1 is controlled by pin17 and Relay2 is controlled by pin16 of your PC.


The power supply **IN** connection is required to power the relays and

12VDC output. The power supply 12VDC output is used to supply the logic (ICs etc.) of each of the K142B kits. We recommend 9VAC or 12VDC from a power adaptor or other similar supply and should have these in stock for less than \$10.

The axis outputs supply step and direction signals to each of the K142B or K142D kits. The AUX I/O terminals can generally be connected to things like switches etc. that are placed at the limits of the movement of your CNC machine. This is to stop you machine from moving too far, in some cases may not be needed at all. These connections will vary depending on the software you use, check the documentation that comes with your software.













CN1 DB25 R/A MALE


© oatleyelectronics.com

K142A



K142B BASIC KIT DESCRIPTION

K142B is a stepper motor controller that interprets the step and direction signals from the PC into the output sequences required by the stepper motors.





HEATSINKING


If heatsinking is required and only one heatsink is used for all MOSFETS insulation will need to be fitted to each of the MOSFETS. If four separate heat sinks are used (one heatsink fitted between each back to back pair) no insulation is required.

MOTOR CONNECTIONS

To find your correct motor connections measure the resistance of the motor coil wires. If when running your motor vibrates instead of rotating swap connection "A" with "B" or "C" with "D".








K142B

K142D BASIC KIT DESCRIPTION

K142D is a stepper motor controller that interprets the step and direction signals from the PC into the output sequences required by the stepper motors.



NOTE:

The MOSFETs supplied with this kit are suitable for a maximum supply voltage of 30VDC. If you wish to use the maximum recommended supply voltage for the K142 system you will need to change the MOSFETs to IRFZ44Z (TO220 type) or similar, (see our website for pricing etc.). You will require either 4 or 8 depending on the current drawn by your motors.

HEATSINKING

If you use TO220 type MOSFETs you can use additional heatsinking. If heatsinking is required and only one heatsink is used for all MOSFETs insulation will need to be fitted to each of the MOSFETs. If four separate heat sinks are used (one heatsink fitted between each back to back pair) no insulation is required.


ASSEMBLY

Assembly is relatively simple, even the (Surface Mount Devices) SMD MOSFETs are easy to fit. Start by holding a MOSFET in place with a washing peg or similar, then solder the 2 legs of the MOSFET. Next solder the back of the MOSFET to the PCB, this must be done as it forms one of the connections required as well as providing heatsinking.

MOTOR CONNECTIONS


To find your correct motor connections measure the resistance of the motor coil wires. If when running your motor vibrates instead of rotating swap connection "A" with "B" or "C" with "D".


6 WIRE MOTOR DIAGRAM




To confirm motor connections use a multi-meter and measure the resistance of the coils.
 $Y \text{ ohms} = 2 * X \text{ ohms}$

8 WIRE MOTOR DIAGRAM







K142C BASIC KIT DESCRIPTION



K142C is a constant current power supply that is used to supply the correct current to the stepper motors to maintain higher performance.



This kit is recommended for use with a 15-34V power supply and low voltage motors. The ideal situation would be a 33-34V supply with 2-4V motors. The K142C is adjustable to suit motors from around 0.5A to 2.5A. By changing the values of R6 and/or R7 lower and higher ranges can be achieved. See construction notes for details.

CONSTRUCTION

Fit the transistors and the regulators to the PCB as shown but do not solder them in place. Remove the insulating pad from the heatsink, cut it in half and punch a hole in one end of each piece as shown. These insulators are used between the LM317 regulators and the heatsink but are not required for the transistors. Remove the regulators and transistors from the PCB and attached them to the heatsink, Make sure to fit the insulating washer to the screw that holds IC1, do not tighten the screws. Now fit the heatsink and it's components to the PCB. Make sure that the components are flat against the circuit board and solder them in to the PCB. Now tighten the screws.





To change the current adjustment range select a new resistance for R6 and R7 using the calculation bellow. Remember that this will set the minimum current, you should select a minimum current below what is required so to allow for adjustment above and below the required current.

$$1.25 / \text{Amps out} = \text{Ohms}$$


$$1.25 \text{ divided by the required minimum current} = \text{resistance in ohms}$$


You may need to place resistors in parallel or series to obtain the resistance needed as shown in the next image. Note that the top connections of R6 and R7 are connected together for series connection.

To set the current apply your power supply to the input terminals of the k142C, connect an amp meter or multi-meter to the output terminals and adjust VR1 to set the desired current.



NOTE:
Some circuit boards may have incorrect output labeling.
The correct terminal connections are as shown in the component layout image on the next page .







NOTE:

Some circuit boards may have incorrect output labeling. The correct terminal connections are as shown here.

Wiring diagram for a full 3 axis system using K142B kits for 4 wire motors



Wiring diagram for a full 3 axis system using K142D kits for 8, 6, and 4 wire stepper motors



NOTE!

Due to an error in the design of this circuit board a small track was omitted. This track should have been between the large pad behind each MOSFETs and the track that passes between the legs of each MOSFET. The metal tag of each MOSFET is also connected to the stump of the middle leg of each MOSFET. To fix this error simply solder a short wire link as shown in the diagram.

