

| | A | B | C | D |
|----|------------------------------------|----------------|---|----------------|
| 1 | IBM TRANSISTOR REPLACEMENTS | | | |
| 2 | IBM TYPE | IBM P/N | COMMERCIAL EQUIVELENT (via: Bob Hunter, Natick) | PACKAGE |
| 3 | 003 | | 2N64 | |
| 4 | 004 | | 2N113 | |
| 5 | 008 | | 2N113 | |
| 6 | 013 | 344892 | 2N1303, 2N1309 | |
| 7 | 014 | 345763 | 2N1303, 2N1309 | |
| 8 | 015 | 526797 | 2N380, 2N502A, 2N247, 2N384, 2N500 | |
| 9 | 016 | 526880 | 2N380 | |
| 10 | 017 | | 2N380 | |
| 11 | 018 | 347592 | 2N380 | |
| 12 | 019 | 389000 | 2N380. | |
| 13 | 020 | | 2N1303, 2N1309 | |
| 14 | 021 | 526796 | 2N1303, 2N1309 | |
| 15 | 022 | 526898 | 2N174, PG-5 | |
| 16 | 023 | | 2N1038 | |
| 17 | 025 | 318322 | 2N1303, 2N309, 2N1381 | |
| 18 | 026 | 535441 | 2N270, 2N324, 2N404, 2N526, R212XC | |
| 19 | 028 | 610371 | 2N1038, 2N1039, 2N1040, 2N1041, 2N1042, 2N1043 | |
| 20 | 029 | 492451 | 2N527, R212XC | |
| 21 | 030 | 369099 | 2N224, R212 | |
| 22 | 032 | 369100 | 2N705, 2N2894* , GL-77 | |
| 23 | 033 | 318324 | 2N1303, 2N1309, 1-D, 2N274, 2N503, 2N368 | |
| 24 | 034 | 535009 | 2N1303, 2N1309, 1-D | |
| 25 | 035 | 492452 | 2N1303, 2N1309, 1-D | |
| 26 | 036 | 207363 | 2N456, 2N1159, PG-14, 2N1383 | |
| 27 | 037 | 208196 | 2N173, 2N441, 2N442, PG-5 | |
| 28 | 038 | 208197 | 2N379, 2N1412, PG-5, 2N378 | |
| 29 | 039 | | 2N705, 2N2894* , 2N706 | |
| 30 | 042 | 369108 | 2N242, 2N379, 2N669, PG-20, 2N243, 2N257, 2N268, 2N301, 2N392, 2N1168 | |
| 31 | 043 | | 2N705, 2N2894* | |
| 32 | 044 | 369119 | 2N43, 2N44, 2N464, 2N465, 2N467, 2N1008B, 2N1191, 2N1193, | |
| 33 | 046 | 369109 | 2N1303, 2N217 | |
| 34 | 047 | 369113 | 2N2904, 2N1132, T3517 | |
| 35 | 049 | 209001 | 2N277, PG-5 | |
| 36 | 050 | 369205 | 2N553, PG-14 | |
| 37 | 063 | 344891 | 2N377, 2N1302 | |
| 38 | 071 | 492450 | 2N377, 2N647, 2N1302 | |
| 39 | 075 | 318323 | 2N377, 2N647, 2N1302 | |
| 40 | 083 | 318325 | 2N388, 2N1302 | |
| 41 | 084 | 369390 | 2N1893, T4200 | |
| 42 | 085 | | 2N1302 | |
| 43 | 086 | 369087 | 2N214, 2N557 - not 2N228, not 2N188, corrected by Bob Feretish | |
| 44 | | 369654 | 2N1302, 2N1304 | |
| 45 | 087 | 369123 | 2N228 | |
| 46 | 088 | | 2N228, 2N1304 . | |
| 47 | 089 | 369559 | 2N228 | |
| 48 | 090 | | 2N228 | |
| 49 | 091 | 369561 | 2N214, 2N228, 2N557, 2N1302 | |
| 50 | 092 | 369562 | 2N228 | |
| 51 | 093 | 369560 | 2N228 | |
| 52 | 094 | 369081 | 2N228 | |
| 53 | 095 | 369205 | 2N228 | |
| 54 | 096 | 369110 | 2N1302 | |
| 55 | 097 | 369114 | SL-100, T3111 | |
| 56 | 098 | 369126 | 1341, 3013, 2N708 | |
| 57 | 099 | 369213 | 2N1302 | |
| 58 | 100 | 369134 | T4200, SL-2, 2N1893, 2N1613 | |

| | A | B | C | D |
|-----|-----|-----------------|--|------|
| 59 | 101 | 369177 | 2N705, 2N2894* , GL-77 | |
| 60 | 102 | 369179 | 2N705, 2N2894* , GL-77 | |
| 61 | 103 | 369180 | 2N705, 2N2894* , GL-77 | |
| 62 | 104 | 369182 | 2N705, 2N2894* , GL-77 | |
| 63 | 105 | 369183 | 2N705, 2N2894* , GL-77 | |
| 64 | 106 | 369194 | 2N705, 2N2894* , GL-77 | |
| 65 | 107 | 369195 | 2N705, 2N2894* , GL-77 | |
| 66 | 108 | 369214 | 2N155, 2N256, 2N307A, PG-5 | |
| 67 | 112 | | 2N705, 2N2894* | |
| 68 | 113 | 477282 | PG-20 | |
| 69 | 114 | 369608 | 2N1303, 2N1309 | |
| 70 | 116 | | 2N1309 | |
| 71 | 117 | | 2N1303 | |
| 72 | 118 | 369204 | 2N527, 2N1038, 2N1039, 2N1040, 2N1041, 2N1042, 2N1043, 2N1044, 2N1045, 2N307 | |
| 73 | 119 | 369616 | PG-20, 2N155, 2N256, 2N307, 2N1309 | |
| 74 | 120 | 369628 | 2N247, 2N380, 2N1515, 2N1517 | |
| 75 | 121 | | 2N1309 | |
| 76 | 122 | 369641 | 2N2411, SL-35 | |
| 77 | 123 | 369648 | 2N2552, 2N2553, 2N2554, 2N2555, 2N2556, 2N2557, 2N2558 | |
| 78 | 124 | 369656 | 2N705, 2N2894* , GL-77 | |
| 79 | 125 | 483012 | 1-D, 2N1303, 2N1309 | |
| 80 | 127 | 369659 | 2N1303, 2N1309 | |
| 81 | 128 | 369662 | 2N1142, 2N705, 2N2894* | |
| 82 | 129 | 369664 | 2N1309 | |
| 83 | 130 | 369667 | PG-20, 2N456, 2N1159 | |
| 84 | 131 | 369682 | 3517, SL-33, 20904, 2N2696 | |
| 85 | 132 | 2414801-1766936 | PG-7 | |
| 86 | 133 | 2414803 | PG-20 | |
| 87 | 134 | 2414806-2703799 | 2N1038, 2N1039, 2N1040, 2N1041, 2N1042, 2N1043, 2N1044, 2N1045 | |
| 88 | 135 | 2414848 | 2N705, 2N2894* , GL-77 | |
| 89 | 136 | 2414877 | FT0019, 2N3251 | |
| 90 | 138 | 2414918 | 2N2696, 3517, 2904 | |
| 91 | 139 | 2414938 | 2N2411, SL-35 | |
| 92 | 141 | 2414947 | FT0019, 2N2411, 2N3251 | |
| 93 | 142 | | 2N2904 | |
| 94 | 143 | 2414971 | FT0019 | |
| 95 | 150 | 2391139 | 2N2904 | |
| 96 | 151 | 369215 | 2N955 | |
| 97 | 152 | 369587 | 2N955 | |
| 98 | 153 | 369588 | 2N955 | |
| 99 | 154 | 369589 | 2N955 | |
| 100 | 155 | | 2N955 | |
| 101 | 156 | | 2N955 | |
| 102 | 157 | | 2N955 | |
| 103 | 158 | | 2N955 | |
| 104 | 159 | | 2N955 | |
| 105 | 160 | 369669 | 2N955 | |
| 106 | 161 | 369683 | 2N955 | |
| 107 | 162 | | 2N955 | |
| 108 | 164 | | 2N955 | |
| 109 | 165 | | 2N955 | |
| 110 | 167 | 369597 | 2N388, 2N302 | |
| 111 | 168 | 369602 | 42C6, 2N2193, 2N2863 | |
| 112 | 169 | 369605 | | 1341 |
| 113 | 170 | 369609 | 2N377, 2N647, 2N1302 | |
| 114 | 171 | 369618 | 4205, SL-14, 2N1613 | |

| | A | B | C | D |
|-----|-----|----------|--|------|
| 115 | 173 | 369624 | 4200, SL-14, 2N1893, 2N1613 | |
| 116 | 174 | 369625 | 1343, SL-23 | |
| 117 | 175 | 369632 | 5B, 2N989, 2N2418, 2N2419, 2N999 | |
| 118 | 178 | 369686 | T4206, SL-98, 2N3252, 2N2863 | |
| 119 | 179 | 369687 | 74206, PC-80, SL-08, 2N2863, 2N3252 | |
| 120 | 180 | 369688 | SL-98, 2N3252, 2N2863 | |
| 121 | 181 | 369689 | SL-5, 2N3252, 2N2863 | |
| 122 | 182 | 369690 | 0110, SL-14, 2N3252, 2N2863 | |
| 123 | 183 | 369691 | T4206, SL-14, 2N3252, 2N2863 | |
| 124 | 184 | 369692 | SL98, 3252, 2N2863 | |
| 125 | 185 | 369693 | 2N2863, 2N862 | |
| 126 | 186 | 369694 | SL-2, 2N2537 | |
| 127 | 187 | 369695 | SL-5, 2N2537 | |
| 128 | 188 | 369696 | 0018, SL-14, 2N3252, 2N2863 | |
| 129 | 189 | 2414972 | H84 | |
| 130 | 190 | 369697 | SL-14, 2N3252, 2N2863 | |
| 131 | 192 | 2414804 | 2N1302 | |
| 132 | 193 | 2414811 | 2N3011 | |
| 133 | 194 | 2414818 | SL-1, FT1312, 2N774 | |
| 134 | 201 | 2391132 | | 3517 |
| 135 | 203 | 2391160 | | 1303 |
| 136 | 204 | 2391201 | PG-5 | |
| 137 | 205 | 2391208 | T3517, 2N2904 | |
| 138 | 206 | 2391237 | T1713, 2N2894 | |
| 139 | 207 | 2391240 | T1713, 2N3829. | |
| 140 | 208 | 2391243 | 2N3304 | |
| 141 | 209 | 2391246 | GL-77, 2N964 | |
| 142 | 216 | 2391328 | GL-77, 2N705, 2N2894*' | |
| 143 | 219 | 2391733 | PG-7 | |
| 144 | 251 | 2414849 | 2N2484 | |
| 145 | 252 | 2414863 | SM3298 | |
| 146 | 253 | | 2N774 | |
| 147 | 254 | 2414878 | 2N1893, 2N1613 | |
| 148 | 255 | 2414879 | SL-23, 2N706 | |
| 149 | 256 | 2414880 | 2N2639 | |
| 150 | 257 | 2414892 | PL-28, H-85 | |
| 151 | 258 | 2414900 | 3N74 | |
| 152 | 259 | 2414921 | SL-5, 2537, 2N2848 | |
| 153 | 260 | 2414922 | SL-4, T4206, 2N2863 | |
| 154 | 261 | 2414923 | | 4205 |
| 155 | 263 | 2414944 | PL-14 | |
| 156 | 265 | 2414950- | 2N744 | |
| 157 | 266 | 2414952 | H-84 | |
| 158 | 267 | 2390102 | SL-97, 2N3252, 2N2537 | |
| 159 | 268 | 2390103 | SL-97, 0125, 2N3252 | |
| 160 | 269 | 2390101 | SL-97, 2N3252, 2N2537 | |
| 161 | 270 | 2390104 | SL-97, 2N2537, 2N3252 | |
| 162 | 272 | 2414974 | 2N2484 | |
| 163 | 273 | 2414977 | 0018, SL-2, 2N2863 | |
| 164 | 274 | 2391015 | SL-26 | |
| 165 | 275 | 2391019 | PL-28 | |
| 166 | 278 | 2391057 | | 1302 |
| 167 | 279 | 2391059 | PL-14, H-84 | |
| 168 | 283 | 2391114 | H-86, 2N3418 | |
| 169 | 284 | 2391117 | T4206, PC-80, SL-98, 2N3252 | |
| 170 | 285 | 2391118 | T0018 | |
| 171 | 286 | 2391131 | FT0018 | |
| 172 | 288 | 2301145 | 2N930 | |
| 173 | 289 | 2391155 | 2N3011 | |

| | A | B | C | D |
|-----|-----|---------|-----------------------|------|
| 174 | 290 | 2391156 | T0062, 2N3013 | |
| 175 | 291 | 2391170 | SL-98, PC-80 | |
| 176 | 292 | 2391171 | H-84, PL-82, 2N3418 | |
| 177 | 293 | 2391184 | 2N3252, 0125, SL-97 | |
| 178 | 294 | 2391207 | 2N3252 | |
| 179 | 295 | 2391224 | 2N2639, 10-H | |
| 180 | 296 | 2391236 | T0059, 2N3303 | |
| 181 | 297 | 2391238 | T0016, 2N3011 | |
| 182 | 298 | 2391241 | T0062, 2N3013 | |
| 183 | 299 | 2391242 | T1211, 2N918 | |
| 184 | 300 | 2391245 | 1211, 2N918 | |
| 185 | 351 | 2391272 | 2N918 | |
| 186 | 353 | 2391313 | 2N2243 | |
| 187 | 354 | 2391319 | 2N3252, 4206 | |
| 188 | 355 | 231329 | SL-1, FT1312 | |
| 189 | 357 | 2391345 | PL-64, 2N3771 | TO-3 |
| 190 | 358 | 2391346 | PL-64, H-98, 2N3771 | TO-3 |
| 191 | 359 | 2391347 | SL-87 | |
| 192 | 361 | 2391367 | PL-14 | |
| 193 | 363 | 2391666 | 0125, 2N3252 | |
| 194 | 364 | 2391667 | PL-64, 2N3772 | TO-3 |
| 195 | 365 | 2391723 | SL-87 | |
| 196 | 366 | 2391766 | FT0047, SL-97, 2N3252 | |
| 197 | 367 | 2391806 | SL-87 | |