




CARRIER CUTOFF TOO LONG



Cutoff Length Approx. 1.5X Material Thickness Max.

Solution: Terminal Out of Position, Adjust Tooling Baseplate

Figure 1