


LOCK TANGS BENT



Solution: Verify Terminal is Not Being Damaged During De-Reeling From the Terminal Reel or Damaged When Bundled Terminated Wires Are Handled.

Figure