





"BANANA" TERMINAL

(EXCESSIVE BENDING OF TERMINAL)

Mating Section and Crimp Section Center Lines Not Parallel



Good Crimp



Solution: Adjust Holddown Pin on Crimp Press

Figure