

On-Off-switches A

1-pole

L1



T1

60°

1

48 □ 20A
32A

M10H . x x x x x¹⁾ - . **A1**
M20 . x x x x - - . **A1**

64 □ 32A
50A

N20 . x - x - x x . **A1**
N33F . x x x - x - . **A1**

88 □ 63A
90A
115A

N40 . x - x - x - . **A1**
N61 . x - x - x - . **A1**
N80 . x - x - - - . **A1**

132 □ 150A
250A

N100 . x - x - - - . **A1**
N200 . x - x - - - . **A1**



+003

