


2-pole, for
3 current transformers
or direct current
measurement
in 3 phases



90°

6	48 □	20A 32A	M10H . M20 .	x	x	x	x	x ¹⁾	-	. M32 . M32
				x	x	x	-	-	-	
64 □	32A 50A		N20 . N33F .	x	-	x	-	x	x	. M32
				x	-	x	-	x	-	. M32
88 □	63A 90A 115A		N40 . N61 . N80 .	x	-	x	-	x	-	. M32
				x	-	x	-	x	-	. M32
				x	-	x	-	-	-	. M32
132 □	150A 250A		N100 . N200 .	x	-	x	-	-	-	. M32
				x	-	x	-	-	-	. M32

