


12 steps



30°

6	48 □	20A 32A	M10H . M20 .	x x x x x x	- -	x ¹⁾ - - -	. ST121 . ST121
	64 □	32A 50A	N20 . N33F .	x - x x - x	- -	x x x -	. ST121 . ST121
	88 □	63A 90A 115A	N40 . N61 . N80 .	x - x x - x x - x	- - -	x - x - - -	. ST121 . ST121 . ST121
	132 □	150A 250A	N100 . N200 .	x - x x - x	- -	- - - -	. ST121 . ST121

