

Installation Instructions

Connector Attachment

Bulletin 7547685 Page 1 of 1

For Braided Cable CNT-240

N Male, Captivated Pin,

Crimp-type Body: 240APNM-C-CR



240APNM-C-CR

1 Remove 15.0 mm (0.591") of Jacket only.

2 Trim 7.0 mm (0.276") of braid, exposing foam.

3 Remove 4.0 mm (0.157") of foam, exposing center conductor.

4 Chamfer the center conductor at a 45° angle.

5 Slide part A onto cable, splay out braid as shown.

6 The cable attachment must be straight and aligned with the hole of connector inner contact. Insert the cable attachment into connector body until stopped; the cable center conductor must be inserted into inner contact fingers. Make sure the braid covers on body sleeve and push part A onto braid.

7 Crimp the ferrule at the area as shown. Crimp tool part number is: CTBC-2.

	表一 有毒有害物质或元素名称及含量标识格式					
	有毒有害物质或元素					
部件名称 (Part Name)	铅 (Pb)	汞 (Hg)	镉 (Cd)	六价铬 (Cr6+)	多溴联苯 (PBB)	多溴二苯醚 (PBDE)
连接器 (Connector)	X	O	O	O	O	O

O: 表示有毒有害物质在该部件所有的均质材料中的含量均在SJ/T 11363-2006规定的限量要求以下。
X: 表示该有毒有害物质至少在该部件的某一均质材料中的含量超出SJ/T 11363-2006规定的限量要求。



Installation Training Available at Andrew Institute

Notice: Andrew disclaims any liability or responsibility for the results of improper or unsafe installation, in spection, maintenance, or removal practices

Andrew Corporation

3 Westbrook Corporate Center, Suite 900, Westchester, Illinois U.S.A. 60154

+1 (708) 349-3300 Fax (U.S.A.): 1-800-349-5444

www.andrew.com

Customer Service, 24 hours

U.S.A., Canada, Mexico: 1-800-255-1479

U.K.: 0800 250055

Other Europe: +44 592 782 612