≓

reserved A-MP(19)

<u>څ</u>

CONNECTOR PRODUCTS DIVISION



# ASSEMBLY INSTRUCTIONS FOR A-MP\* 42 POSITION SERIES "M" CONNECTORS

IS 7	179
RELEASED	10-15-64
REVISED	




Fig. 1

1. These instructions cover the A-MP 42 Position Series "M" Connectors shown in Figure 1. Read them carefully before assembling the Connector.

## 2. CONTACT SELECTION

- (a) Select proper A-MP Miniature COAXICON\* Contacts for use in these Connectors from AMP Instruction Sheet No. 1770.
- (b) Select A-MP Type II, III or III Plus Contacts for use in these Connectors from AMP Instruction Sheet No. 1379.

### 3. CONTACT CRIMPING

(a) Crimp A-MP Miniature COAXICON Contacts according to AMP Instruction Sheet No. 1770.

(b) Crimp A-MP Type II, III and III Plus Contacts using the Tools and instructions referenced on AMP Instruction Sheet No. 1379.

## 4. CONTACT INSERTION

- (a) Push Contact all the way into Connector Block. See Figure 1.
- (b) Pull back lightly on Wire to make sure Contact is properly inserted.

NOTE: When inserting Contacts crimped to small, flexible Wire, use AMP Insertion Tool No. 91002.

<sup>\*</sup>Trademark of AMP Incorporated




Fig. 2

#### 5. CONTACT EXTRACTION

- (a) Extract A-MP Miniature COAXICON Contacts according to AMP Instruction Sheet No. 1770.
- (b) Remove A-MP Type II, III and III Plus Contacts using A-MP Extraction Tool No. 305183. See AMP Instruction Sheet No. 1216.

## 6. PANEL MOUNTING

- (a) Make a cutout in the Panel using the Panel Cutout Dimensions in Figure 2.
- (b) Mount the Connector Block to the Panel using A-MP Series "M" Guide Pins and Sockets (see AMP Instruction Sheets No. 7054 or 7055) or 4-40 Screws.

NOTE: The AMP Instruction Sheets referenced above are packaged with A-MP Tools, Connectors and Accessories.