


2-pole



60°

1	48 □	20A 32A	M10H . M20 .	x x x x x x x x	x ¹⁾ - - -	. A2 . A2
	64 □	32A 50A	N20 . N33F .	x - x - x x x -	x x x -	. A2 . A2
	88 □	63A 90A 115A	N40 . N61 . N80 .	x - x - x - x - x - x -	x - x - - -	. A2 . A2 . A2
	132 □	150A 250A	N100 . N200 .	x - x - x - x -	- - - -	. A2 . A2



+003

