




GECKODRIVE INC. JUNE 16, 2002 - modified Feb, 20, 2005

NOTE: Removed 100k resistor by power supply
Changes D5 to a 12 V Zener, 1N759

Post - 3755 Mariss notes correct diode voltage