

LIGHTHOUSE

The magazine of the Eddystone Users Group

INDEX

Issues 1 – 96 combined
SETS SECTION



Combination of Anthony Richards Indexes in searchable pdf format

Alan Ainslie April 2009

INDEX TO EDDYSTONE MODELS

	issue	page
31A		
featured receiver-----	32	29
manual -----	19	11
40A		
brief description -----	5	1
mains psu danger -----	25	7
narrow band filters, query as to -----	37	24
41A		
brief description -----	7	2
160		
services equivalent of ECR -----	21	9
214/215		
brief description -----	24	9
-----	36	13
-----	38	25
358		
advert, reprint (1942)-----	3	7
(1944) -----	21	5
Australia, used in-----	29	29
condensers, paper -----	37	8
crystal, dud -----	39	20
dates when current -----	23	17
EB34 diode valves, replacement of with 1N914 diodes -----	42	20
electric shock -----	4	5
filters, crystal-----	42	20
Gulf War, monitoring of -----	8	1
mechanical problems -----	40	18
motorboating -----	7	5
Norway, in use, ex WW II trawler -----	8	16
output valves -----	35	23
overhaul-----	10	17
-----	10	22
rescued from burial (Dave Langdon) -----	21	10
Royal Navy designation B34 -----	42	10
S meter, sticking-----	12	14
valves, ECC82 replacing EF39 -----	25	15
vhf coils-----	14	7
-----	21	9
400		
brief description -----	18	10
-----	24	10
-----	29	11
-----	31	22
valves, ECC82 replacing EF39 -----	25	15
440		
brief description -----	12	24
-----	36	7

	issue	page
450	brief description -----36	7
504	featured receiver-----21	3
	acquisition by member -----16	3
	advert (N.Z.) -----18	5
	a.f. gain, fault -----10	14
	alignment frequencies -----4	3
	a.v.c., fault-----10	14
	brief description -----29	11
	drifting, curing-----40	5
	rejuvenation of-----32	14
	-----39	14
	S meter, zeroing problems-----42	17
	valves, ECC82 replacing EF39 -----25	15
	556/B p.s.u. -----20	9
556	alignment frequencies -----4	3
	comparison with 504 -----15	1
640	featured receiver-----6	2
	advert -----6	12
	-----9	23
	-----27	32
	-----33	11
	-----42	27
	Arnold & Wright, N.Z. -----37	26
	a.f. gain, increase causing howl-----19	2
	agc, not working-----6	9
	alignment frequencies -----4	3
	audio output, distorted-----17	6
	audio output, lack of-----6	9
	-----9	9
	-----11	3
	bandspread, not working-----12	2
	bfo, rustling noise at zero beat -----10	9
	-----29	17
	components, needing changing in most sets -----10	13
	crystal phasing, reversed to eliminate QRM-----31	2
	drifting -----34	21
	electrolytic condensers -----3	2
	-----34	8
	faults, common -----6	9
	typical -----33	19
	frequency jumping -----34	29
	fuse, ht, fitting of-----36	27
	handles, chrome -----34	20
	hum -----3	2
	-----11	4
	-----33	22
	i.f. breakthrough-----27	14
	-----39	7
	in use (Peter Stein)-----27	16
	loudspeaker, fitting of-----33	23
	mixer valve-----34	26
	modifications, factory (early models)-----31	8
	motorboating-----10	14
	-----25	16

640 cont'd

noise limiter, non - operational -----	6	9
-----	12	14
output stage -----	8	6
fault -----	27	25
overhaul -----	5	5
overheating -----	8	2
-----	12	14
pre-production models on trial -----	17	3
product detector, fitting of -----	29	19
QRP transmitter within -----	11	3
-----	13	4
-----	15	21
prices, new -----	11	17
rectifier, OZ40, use of -----	28	17
resistor upgrading -----	25	7
renovation -----	32	13
restoration from scrap (James Scott) -----	18	19
rf gain pot., use of correct type -----	36	2
RSGB show article -----	16	2
S meter -----	4	2
-----	6	9
tuning dial, slippage -----	24	1
upgrading very early models -----	10	24
usage & repairs -----	18	7
valves, ECC82 replacing EF39 -----	25	15
valves, metal, shock warning -----	31	17
valves, miniature, fitted -----	30	18
1948 station re-creation, use in -----	27	9

659

advert, factory -----	9	22
-----	42	27
alignment frequencies -----	4	3
gain, low -----	28	27
magic eye -----	16	1
not working -----	32	14
-----	33	33
repair and cleaning -----	12	9
repair -----	20	10
resistor fault -----	14	11
switch, on/off, faulty -----	14	12
valve cap wiring -----	17	5
valves, ECC82 replacing EF39 -----	25	15
659/670 model, querying existence of -----	21	17

670

featured receiver -----	4	8
alignment frequencies -----	4	3
battery powered -----	41	25
bfo, fitting -----	17	12
-----	26	28
brief notes (Bert Swanley) -----	15	14
dial light failure, repeated -----	22	18
distortion, reduction of -----	29	13
drifting -----	16	5
dropper resistor corrosion -----	33	20
faults, common -----	17	6
frequency coverage, gap in -----	16	3
hum -----	12	14
-----	32	15

670 cont'd

long wave coils fitted (Ken Quigg)-----	32	15
modifications, found on set-----	21	18
overhaul-----	10	21
rectifier, substitute -----	21	8
Seafarers Receiver -----	28	28
tuning, backlash -----	18	17
valves, substitutes -----	7	1
-----	22	18
670/1 MIMCO 2232B-----	5	2
670/A MIMCO 2245A -----	9	7

670A

featured receiver-----	33	5
avc, not working-----	9	12
dial lights, fitting of-----	22	5
lack of -----	23	20
early model acquired by member (Bill) -----	42	26
fan, fitting -----	9	8
faults, common -----	6	9
-----	17	6
ferrite core, loose-----	27	22
Gulf War, monitoring of -----	32	17
hum -----	4	4
mains voltage, using down to 80 volts-----	23	11
modifications-----	20	5
SW Magazine, described in-----	34	11
overheating-----	8	2
rebuilding-----	9	9
-----	23	9
after transistor 'conversion' -----	15	11
repairs -----	33	14
sensitivity, low-----	6	3
selectivity, poor-----	5	3
thermistor-----	6	9
valve sockets, dirty-----	33	20

670C

featured receiver-----	27	5
aerial input ohms -----	34	2
AC only conversion-----	27	7
follow - up comments-----	35	17
-----	36	35
bfo, fitting of-----	27	7
faults, common -----	17	6
hum, curing-----	19	6
knobs, size of -----	16	15
originality, member's set -----	34	10
rf gain noisy-----	13	12
tape recorder output -----	26	18

680

featured receiver-----	29	3
advert for -----	14	18
-----	29	5
alignment frequencies -----	4	3
bass, lack of-----	33	20
bfo, fault -----	33	8
'customised' version-----	24	18
differences between early and later models-----	25	12
-----	29	27
drift -----	12	14

680 cont'd

history of one since new (Ellis Taylor)-----	14	18
New Zealand models -----	12	22
-----	14	4
-----	29	11
ssb reception mod. -----	32	21
tuning scale, backlash -----	33	20
variable bandwidth system-----	34	14

680X

featured receiver-----	5	7
aerials -----	35	18
bfo, improving -----	28	19
crystal calibrator, fitting within -----	28	8
drifting -----	6	3
faults, common -----	6	11
New Zealand, used for monitoring & later restored-----	37	23
noise limiter, fault-----	9	10
non - operational (faulty resistor)-----	22	6
S meter, fault-----	29	14
-----	42	21
selectivity -----	11	10
switches, toggle-----	29	9
(mains) -----	40	2
transformer, mains, burnout -----	24	16
variable bandwidth system-----	34	14

700

brief description -----	24	9
blueprint found ('Queens' model') -----	38	12

710

alignment frequencies -----	4	3
-----------------------------	---	---

710B

see All World Six

720

audio response curve -----	39	15
graph-----	39	16
brief description -----	34	26
discovered at factory-----	39	19
parts list obtained -----	39	1
Yachtsman variant -----	21	17

730

featured receiver (730/4)-----	17	8
advert, reprint-----	4	11
crystal switch-----	17	3
fault finding -----	40	28
mains switch, failure & replacement -----	42	15
most prolific model -----	17	18
noise limiter, incorrectly wired when new -----	30	24
Radio Bygones, featured in-----	28	1
Short Wave Magazine, featured in -----	28	7
switches, replacing -----	42	15
variable bandwidth system-----	34	14
variants of models-----	17	12
730/1, revalving -----	10	18
730/4 calibrator, weak-----	8	19
calibrator fault -----	22	18
faults, resistors -----	2	6
ht on/off switch -----	14	18
hum -----	8	19
modifications, reversible -----	35	12

730 cont'd

730/4 oscillating at af stage-----	41	19
product detector (add-on)-----	18	18
-----	19	12
-----	29	19
rf amplifier mod -----	35	17
730/5 brief description -----	18	12
730/6, digital readout conversion-----	14	9

740

featured receiver-----	3	5
a.f. coupling fault-----	23	17
alignment frequencies -----	4	3
auxiliary supply plug -----	10	14
crystal calibrator, fitting of -----	27	10
Elbe barge, used in-----	21	13
emission, loss of-----	12	18
faults, common -----	6	10
H.T., lack of-----	7	5
motorboating-----	26	2
octal plug on rear-----	12	13
-----	28	20
output, lack of-----	32	14
overhaul-----	7	4
-----	8	7
-----	15	9
Q Fiver, use with -----	27	3
-----	29	15
repairs & mods -----	33	17
transformer, mains, protection of-----	29	13
valves, blown -----	35	11

750

featured receiver-----	12	19
alignment frequencies -----	4	3
Buenos Aires owner -----	21	13
bfo, noisy -----	8	14
lack of-----	10	15
case renovation -----	9	11
circuit diagram incorrect -----	31	13
current feedback-----	26	14
date of launch-----	16	15
earth connection problem-----	22	18
faults, common -----	6	10
gain, low -----	12	14
hum, curing-----	42	21
instability, full volume -----	7	6
Marconi HR100, equivalent of 750/2-----	19	18
microphonic-----	12	14
output stage, description -----	28	29
overhaul-----	8	17
overheating-----	8	3
product detector, fitting of-----	29	19
realignment-----	18	9
Super model, query as to existence of -----	16	13
-----	17	12
-----	20	3
tape recording outlet-----	22	17
transformer, mains -----	8	2
tuning ratio -----	12	1

750 cont'd

valve substitution, 6AQ5 to replace N78-----	26	14
-----	34	28
voltage stabiliser -----	10	16
750A, de luxe model, overhaul of-----	8	11

770M

brief description -----	20	3
-----	24	9
-----	26	24

770R

featured receiver-----	9	19
advert, reprint-----	2	4
aerials -----	7	8
-----	10	8
-----	11	5
Dressler active antenna -----	26	19
China & Brazil, supplied to -----	42	30
drive cord-----	6	9
faults, common -----	6	10
f.m., fault -----	26	4
gain, low -----	14	12
-----	33	13
MoD designation <i>see also R213 below</i>		
-----	33	22
-----	35	14
NASA, used by -----	42	1
-----	42	8
original users-----	2	4
panadaptors, use with-----	6	7
-----	33	31
plug, correct type-----	34	21
R213 MoD designation -----	33	22
-----	38	29
radio astronomy, used for (Jack Read) -----	39	33
repairs to-----	14	14
S meter, fault-----	22	7
-----	22	16
satellite reception-----	32	18
sensitivity, low-----	7	6
-----	8	6
signals, reception of-----	14	10
solar noise, recording of -----	9	4
tuning indicator, faulty -----	22	2
turret tuner, reason for-----	14	10
valves replacement (V1, 2 & 3)-----	24	16
versions -----	4	4
770R/9, used by Diplomatic Wireless Service -----	4	4

770S

brief description -----	4	4
-----	10	11
-----	24	8
-----	32	4
Air Ministry numbering -----	5	11
designer's comments -----	24	9
output, lack of-----	24	8
signals, lack of-----	27	1
turret tuners -----	33	10
valves, cost of-----	30	17
-----	30	24

	issue	page
770U		
advert, reprint-----	2	4
-----	3	4
-----	11	6
drive cord replacement & plan-----	37	3
faults, common -----	6	10
original users-----	2	4
panadaptor, use with-----	28	20
range lamps, intermittent-----	12	13
sensitivity, low-----	7	6
turret tuners -----	33	10
-----	36	14
valves, correct type -----	24	8
variations -----	33	22
793		
projection model -----	26	29
800		
television model -----	26	29
810		
information required by Ted Moore -----	26	30
820		
featured receiver-----	20	3
acquisition and case-----	14	9
case -----	16	3
co-ax sockets-----	29	13
documentation, original -----	34	17
gain, low (faulty resistor) -----	22	7
-----	22	20
in use -----	28	16
reliability -----	27	14
stereo version query -----	21	2
V5, low operating voltage -----	28	30
830		
Addis Abbaba, used in -----	21	14
advert, factory (830/7)-----	22	4
bfo, drifting-----	26	18
Canadian variants -----	26	23
crystal filter, fitting -----	9	24
crystals -----	17	9
diodes, replacement for DD006 -----	34	17
faults, common -----	6	10
modifications, by member -----	42	16
noise limiter fault (6AL5)-----	42	25
not working (condenser fault)-----	22	2
Piccolo, reception of-----	23	15
Piccolo, filter removed -----	9	24
-----	37	2
selectivity switch not connected, Piccolo sets -----	6	5
-----	29	14
triple diversity racks -----	32	12
valves, substitutes -----	7	1
830/2, replacement condensers (Arthur Collins)-----	19	2
830/5, imported from Sweden -----	9	3
830/7, superiority -----	7	11
830/8, Diplomatic Wireless Service -----	1	3
830/11, STC model -----	5	2
830/5, STC model-----	5	2
830/6, use with mechanical morse printer-----	13	5
830/8, AMTOR & RTTY reception -----	11	13

830 cont'd

830/9, local oscillator switch-----	33	29
830/12, frequency coverage-----	19	11

840

featured receiver-----	26	9
advert, Webb's Radio-----	42	4
bfo, modification-----	15	13
dropper resistor, corrosion-----	27	29
faults, common-----	17	6
gain, low		
hum, curing-----	14	11
-----	29	8
live chassis-----	15	13
local oscillator, fault-----	26	17
range switch-----	15	13
ssb, resolving-----	15	13
transformer, 110v-----	15	13
waveband markings-----	15	13

840A

featured receiver-----	1	7
AC only, modification-----	25	14
aerial link, A2 to E-----	7	1
af gain, not fully operational-----	36	35
audio, distortion-----	7	5
avc, improvement-----	10	18
dial light-----	4	4
disabled listener, donated to (by Phil Johnstone)-----	28	10
Dr. No, used in film-----	33	26
drive cord restringing-----	25	17
dropper resistor-----	12	13
-----	26	12
faults, common-----	6	10
-----	17	6
faults, various-----	22	15
-----	23	21
gain, low, curing of-----	20	15
-----	39	17
headphones usage, fault develops-----	10	15
-----	14	11
ht increase, mod-----	33	10
hum-----	10	16
instability, strong signals-----	27	25
noise limiter diodes-----	34	21
overheating-----	8	2
range switch-----	12	8
refurbishment-----	10	12
-----	25	19
-----	30	11
repairs-----	5	3
R.F. & oscillator re-alignment-----	2	2
shipboard use-----	33	21
superiority over Sangean-----	29	1
used overseas (Christopher Wood)-----	39	32
transformer, isolation, fitting of-----	32	6
valve failure-----	15	2
UY41 bypass-----	35	20

	issue	page
840C		
featured receiver-----	7	8
advert, reprint-----	4	11
-----	7	15
aerial, importance of correct impedance -----	41	5
bfo, rustling noise at zero beat -----	10	9
-----	29	17
drive cord-----	11	5
fan, fitting -----	9	8
faults, common -----	17	6
fault, intermittent -----	29	9
frequency shifting -----	28	20
if regeneration mod. -----	32	31
magic eye, fault-----	12	13
-----	26	20
motorboating-----	32	21
oscillating-----	42	31
resistors, explanation of-----	11	9
r.f. / i.f gain, combined control-----	11	5
sensitivity, low-----	4	5
spurious signals-----	35	2
840 II, prototype -----	10	15
850		
featured receiver-----	39	3
broadcast breakthrough -----	33	9
earthquake prediction-----	21	2
electrolytic failure-----	26	4
elf & vlf signals, used for -----	32	19
NDB reception, used for -----	21	16
850/4, manual, errors in -----	37	8
870		
featured receiver-----	24	3
bfo fitting -----	17	12
brief description -----	30	7
choke, burnt out -----	22	5
condenser fault-----	14	11
i.f. rejection circuit-----	16	15
mobile use (Austin A40)-----	23	20
modifications, factory, late models-----	40	26
overheating (rectifier) -----	8	3
overhaul-----	22	13
-----	24	7
-----	25	9
(Dick King)-----	41	9
restoration after transistor conversion -----	23	11
signals, lack of-----	14	12
transistor conversion, inferiority of -----	25	14
valves, types used -----	25	18
870A		
featured receiver-----	36	25
audio, distorted -----	35	13
brief description -----	30	7
checking & overhaul-----	7	7
electrolytic failure-----	42	10
intermittent fault, dry joint-----	13	4
in use (Alan) -----	40	17
modifications to improve (Andy)-----	41	3
output transformer, substitute -----	21	8

870A cont'd

purchase by member		
Billie Coleman -----	16	17
Stan -----	39	10
realigning aerial tuning stage-----	12	13
restoration after bodging-----	29	9
-----	41	27
selectivity increase mod. -----	31	22
ssb reception mod-----	32	7
transatlantic broadcast reception -----	34	11
WVS, obtained from-----	28	10

880

bands, loss of-----	27	28
calibrator, query as to fault -----	38	21
gain, low -----	4	6
(880/2) -----	29	13
noise level -----	17	15
output low, ssb/cw -----	42	29
signal jumping -----	12	8
880/3, Marconi H2301/01 -----	9	24

888

agc, ineffective -----	5	10
calibrator, repair-----	33	14
difference between 888A -----	4	4
-----	8	9
Dr No, used in (not ?) -----	32	4
drifting -----	5	10
-----	41	12
in use worldwide -----	27	1
mains switch, fault -----	34	4
overhaul-----	22	13
repairs -----	13	10
tracking, incorrect-----	27	25

888A

featured receiver-----	23	2
aerial trimmer -----	21	8
bandspreading -----	16	16
calibrator, trimming-----	23	8
condenser, fault-----	14	12
difference between 888-----	4	4
-----	8	9
faults, common -----	6	11
output, lack of-----	14	11
-----	26	15
-----	29	14
resistor, fault -----	14	11
restoration of set-----	23	5
spurious signals-----	11	9
ssb reception -----	22	16
voltage stabiliser -----	8	4

890

brief description -----	10	15
-----	24	10
-----	31	22
discussion of -----	35	27

909A

featured receiver-----	31	17
brief description -----	20	12
diode replacement-----	42	2

	issue	page
909A cont'd		
psu -----	18	17
910		
featured receiver-----	37	5
equivalent of Marconi HR101 -----	26	13
912		
brief description -----	10	15
930		
discussion of -----	35	27
usage of, new -----	17	7
935		
prototype for 940-----	10	15
940		
featured receiver-----	2	7
advert, factory -----	32	26
-----	34	24
a.f. gain pot., failure -----	24	2
audio crackling -----	25	14
audio gain increase mod.-----	31	9
audio output distorted -----	13	6
-----	29	10
-----	19	17
-----	24	2
avc, poor-----	24	2
bfo, 'popping'-----	19	5
bulbs -----	4	2
cathode volts, low -----	10	14
ceramic filters, fitting of (not!)-----	33	4
condenser, overheating-----	8	19
crystal calibrator, modifying for -----	7	2
-----	7	13
-----	24	17
-----	26	1
deaf -----	32	22
dial light, modification -----	24	2
electrolytic failure-----	18	10
faults, common -----	6	11
faults, one member's -----	7	5
fuses, terminals corroded -----	41	13
gain, lack of-----	30	5
hf suffix model-----	29	11
-----	32	5
microphony-----	18	8
MoD version -----	31	1
output, lack of-----	15	2
output transformer, substitute -----	21	8
resistors		
high -----	8	19
burnt out -----	10	16
problems -----	23	7
replacement-----	25	18
-----	29	10
restoration of-----	14	15
sensitivity, lack of-----	17	6
servicing (Graham Leese)-----	12	25
-----	12	16
silverfish found inside new purchase -----	41	4
squelch, fitted -----	8	9
-----	12	12

940 cont'd

transformer, winding-----	12	14
tuning ratio -----	12	1
tuning mechanism -----	26	2

958

featured receiver-----	14	6
advert, factory -----	15	18
comparison of different versions -----	8	13
coupling co-ax corrosion-----	26	11
-----	27	2
-----	37	11
-----	38	2
faults -----	38	9
intermittent function -----	33	19
Isle of Wight museum -----	26	19
MoD reference numbers -----	20	12
overhaul-----	12	15
-----	35	3
prices -----	24	17
servicing -----	17	13
tuning display, fault-----	12	13
958/H, Hagenuk model-----	5	2
958/D, Debeg model-----	5	2
958/5, Nebula, manual -----	19	11

960

featured receiver-----	16	10
battery operation, nicads, problems with-----	38	9
brief description -----	18	12
-----	29	18
bfo, noisy / unstable -----	10	16
-----	13	15
comparison with 940 -----	9	7
-----	26	29
drifting -----	35	6
i.f. rejector tuning -----	10	16
solar powered -----	8	6
transistor change, retrimming -----	9	11
transistor blown, r.f. -----	10	16
variations on later sets -----	32	22

961 MkI & II

information sought -----	39	19
--------------------------	----	----

990R

advert, factory -----	36	31
aerials, suggested types -----	20	8
brief description -----	9	8
-----	36	31
crystal units-----	37	9
drifting -----	42	23
faults, common -----	17	5
frequency deviation, figures sought-----	36	14
i.f. convertor circuit-----	40	14
using with 990R -----	42	7
non working-----	12	4
prices, secondhand -----	27	23

990S

featured Receiver-----	8	7
advert, factory -----	20	13
-----	36	32
faults, common -----	17	5

	issue	page
1000		
featured receiver-----	25	6
1002		
brief description -----	41	1
1004		
bfo fault-----	26	27
MIMCO Sentinel-----	5	2
Redifon -----	5	2
I.T.T. 5 -----	2	
Hagenuk E92-----	5	2
1650		
pcb -----	20	3
1570		
featured receiver-----	35	7
pcb -----	20	3
1590		
board ref. nos.-----	19	5
1837		
availability secondhand -----	33	21
Marconi Pacific-----	26	1
press release, September 1977 -----	16	14
1964		
ex trawlers, purchased by member -----	42	18
1990		
1990R used with panadaptor, HMS Euralyus -----	24	10
1995		
brief description -----	12	8
2004		
brief description -----	24	18
6200		
brief description -----	41	32
All Wave Four		
advert, factory -----	38	11
All World Two		
featured receiver-----	28	25
advert for -----	36	24
refurbishment -----	26	25
review, Wireless World 1936 -----	39	25
All World Four		
brief mention-----	25	4
All World Six		
featured receiver-----	19	15
advert, factory, and specification-----	19	9
Africa, use in-----	24	9
brief description -----	3	5
-----	10	15
repairs -----	33	13
wind generator, powered by-----	9	2
710/B 4 -----	4	
All World Eight		
featured receiver-----	13	16
advert, factory -----	34	12
brief description -----	12	2
-----	12	24
differences between early and late models-----	24	4
R101 version used by RN-----	36	14
Atlantic Two		
brief description -----	33	26
-----	34	15

Atlantic Three		
existence of-----	38	25
Colonial		
query as to existence of -----	36	4
EA12		
advert, factory -----	32	26
chirpy cw reception -----	29	13
gain, low -----	7	12
on certain bands -----	33	20
QRP transmitter within -----	13	5
overhaul & recification of apparent factory faults -----	21	12
peak rf control, faulty -----	14	12
power supply section, failure in -----	42	14
purchased new from G5GX -----	27	9
realignment -----	26	19
RSGB HQ, on display -----	22	11
-----	29	22
S meter scale -----	25	13
incorrect readings -----	42	31
transistor front end considered -----	25	13
using properly -----	27	4
variable bandwidth system -----	34	14
EB35		
featured receiver -----	11	11
aerial		
effect of very long wire -----	34	21
vhf -----	37	31
-----	39	19
air band signals, reception of -----	33	1
audio output		
lack of -----	14	11
-----	33	19
distorted -----	29	14
-----	36	35
battery		
case -----	9	5
-----	37	13
corrosion -----	20	6
operation -----	35	21
bfo, fitting of -----	12	10
-----	16	20
comparison with EB37 -----	30	21
controllable i.f. modification -----	18	16
diode D1 -----	41	28
drifting -----	7	14
Eddystone Lighthouse, presented to -----	11	16
faults, common -----	6	10
headphone socket -----	42	7
identifying features, all models -----	40	31
light switch, modification -----	13	6
-----	16	20
loudspeakers -----	17	6
mains psu		
danger -----	25	7
description -----	37	13
Mk III, differences -----	8	6
mobile psu -----	14	14
NATO release of sets -----	41	25
noise limiter, fitting -----	16	19

	issue	page
EB35 cont'd		
non - working -----	21	16
pcb no. 75328/W -----	33	31
phone socket -----	42	7
psu diodes, replacement-----	34	29
selectivity, improving-----	22	9
-----	37	17
signal, lack of (AM) -----	27	3
stereo version -----	21	2
transistors, whiskers on-----	8	11
-----	37	2
swapping for silicon types (not !)-	34	10
used overseas -----	21	13
EB35 MkII		
differences between Mk I -----	16	19
-----	22	9
Joint Services/NATO stock number -----	13	13
NATO release of sets -----	41	25
psu diodes, replacement-----	34	29
realignment & overhaul -----	29	19
stolen (Ted Moore's rx), serial no. 3176 -----	40	25
EB35 MkIII (Statesman)		
featured receiver-----	34	31
model variants -----	35	8
rf gain, fitting of -----	42	22
EB35A		
brief description -----	7	14
EB36		
advert, factory -----	9	16
acquisition & refurbishment, by member -----	42	17
aerial, ferrite for use with -----	27	19
identifying features-----	40	31
realignment-----	33	7
Reuters, owned by -----	38	10
EB37		
advert, factory -----	15	18
aerial, remote ferrite for use with-----	34	11
bfo, fitting -----	27	15
brief description -----	18	12
ceramic filters, effect of-----	19	2
comparison with EB35 -----	30	21
harmonics caused by faulty diodes -----	26	12
identifying features		
microphony-----	18	8
motorboating-----	14	12
output, distorted -----	14	12
output, lack of-----	18	8
psu diodes, replacement-----	34	29
realignment, considering-----	29	21
solar power -----	29	25
transistors, bewhiskered-----	23	14
EC10		
featured receiver-----	10	3
advert, factory -----	10	0
-----	32	26
battery case-----	9	5
-----	37	13
battery corrosion -----	20	6
battery substitution-----	23	19

EC10 cont'd

bfo, fault -----	33	19
-----	39	17
-----	42	22
ceramic filters -----	19	2
comparison with other receivers -----	16	6
crystal calibrator, fitting -----	14	13
diode D1, failure -----	28	29
-----	41	28
diode and transistor failure (lightning) -----	23	13
drifting -----	12	13
-----	33	19
faults, common -----	6	10
filter problems -----	29	12
filter, modifying for cw reception -----	29	13
Ford Zephyr Mk I, fitted to -----	8	7
Gulf war, monitoring -----	9	1
hiss, curing -----	25	7
identifying features (all models) -----	40	31
model variations (Tor Marthinsen) -----	18	17
loudspeakers -----	17	6
mains psu		
danger -----	25	7
description -----	37	13
output, intermittent -----	20	16
overseas use -----	21	13
power supply		
faults -----	33	18
240v output, caution -----	42	2
Practical Wireless, owned by staff -----	31	11
purchased new (Roy Elwen) -----	38	31
QRM, reducing -----	9	7
r.f. protection -----	10	11
restoration -----	27	17
-----	28	13
scale cursor mis-placed -----	42	29
selectivity, improving -----	37	17
servicing -----	16	6
Short Wave Magazine, featured in -----	28	7
solar power -----	6	3
spurious signals -----	36	3
ssb reception -----	38	31
switches, push button -----	40	2
transistors		
incorrect type fitted -----	27	11
whiskers on -----	8	11
substituting with silicon types (not !) -----	26	28
-----	34	10
transmitter incorporated -----	26	22
ZOO-2530 models, query as to -----	37	1

EC10 MkII

bfo, not working -----	12	13
dial lamps, substituting for LEDs -----	26	8
drifting -----	34	16
-----	42	13
MIMCO 6689 -----	5	2
purchased new from Imhofs -----	37	24
tuning, fine, fault -----	17	5

	issue	page
EC10 Mk III		
brief description -----	7	11
EC10A/2		
brief description -----	8	12
owned by SWM -----	30	14
mobile use, Sunbeam Rapier -----	30	22
ECR		
featured receiver-----	22	3
advert, factory -----	2	1
-----	34	27
-----	37	21
-----	40	30
-----	41	20
dates of manufacture-----	37	29
manual, being compiled-----	34	8
smoothing choke -----	21	8
160 Services equivalent -----	21	9
Edometer		
featured set -----	42	1
-----	42	3
-----	42	5
EK20		
brief description -----	11	2
prototype-----	10	15
query as to -----	17	7
Empire Two		
good receiving ability -----	40	29
EM34		
acquired by member -----	30	5
magic eye weak, curing -----	42	11
E.R.A.		
featured receiver-----	30	3
advert, factory -----	31	27
-----	34	12
comparison with ERA7 -----	32	5
Everyman Short Waver		
featured receiver-----	40	7
brief description -----	39	21
EY11		
brief description -----	24	9
-----	30	19
-----	40	11
discovered at factory-----	41	27
further information (prototype) -----	42	9
Homelander		
retrieved from loft-----	11	2
Kilodyne '4'		
featured receiver-----	18	2
block schematic-----	18	1
found partly built (David Lewis) -----	28	7
information available (circuits etc.) -----	37	12
VIs, used by in WWII -----	42	24
L.P.C.		
advert, factory -----	34	27
-----	41	16
Orion		
brief description -----	25	1
-----	26	27
7000, brief description -----	34	0

	issue	page
R.74		
query whether Eddystone -----	18	17
R.101		
<i>see All World Eight</i>		
R213		
<i>see 770</i>		
Scientific Two		
featured receiver-----	41	10
blueprint available -----	38	29
Scientific Three		
brief description -----	30	19
Scientific Four		
advert for-----	41	14
broadcast stations, list of included in handbook (1927) -----	36	9
construction manual -----	35	23
Short Wave Two		
monitoring, used for in WWII-----	40	33
replica, intention to construct -----	27	16
-----	34	2
Sphinx		
featured receiver-----	15	5
advert, factory -----	15	0
brief notes -----	15	1
circuit-----	15	20
owned by members -----	17	18
-----	12	8
Statesman		
<i>see EB35 Mk III</i>		
Twin		
brief description -----	25	21
replica, intention to reconstruct-----	34	2
-----	42	30
owned by Graeme Wormald-----	30	1
obtained by Graeme Wormald -----	39	11
Ultra Short Wave Radio Telephone		
featured set -----	38	15
constructional article, advert for-----	38	13
Yachtsman <i>see also EY11</i>		
720 variant -----	21	17

INDEX TO EDDYSTONE RECEIVERS

	<i>issue</i>	<i>page</i>
31A		
brief description	46	6
358		
acquired by Graeme Wormald	43	6
advert for	43	12
drifting, cure	44	15
early and late sets, differences	48	22
Webbs Radio advert	43	12
504		
scale plate photocopy available.....	44	27
values of, current.....	44	9
640		
headphones, use of modern type	48	25
tuning mechanism, description & maintenance	43	9
.....	46	4
usage under modern conditions.....	46	22
670		
differences between MIMCO variant.....	43	28
use of UAF42 valve in lieu of UAF41	43	10
670A		
audio, low	48	24
hybrid set	44	24
MIMCO 2245A, comparison with	45	30
680		
advert for, Norwegian.....	44	10
superior selectivity over 940	43	28
use as audio amplifier.....	45	3
680X		
drifting.....	48	23
selectivity comment.....	43	30
700		
in use on Gaelic Ferry	43	30
710		
advert for, Norwegian.....	44	10
vibrator units, possible source.....	48	28
730		
730/4		
ease of dismantling & transporting	44	4
product detector, modifying for	48	4
repainting	46	28
740		
Braille model, owned by Howard Turner.....	43	6
purchase & restoration, Peter Lankshear	43	41
repairs, various	46	4
valve replacement needed	48	27

750		
	advert for, Norwegian.....	44 10
	refurbishment by member (Pete Roberts)	48 3
770R		
	aerials to use	46 7
	'M' suffix, info. required	44 6
	Panadaptors, use with	45 30
	unusual variant	45 13
	used by General Electric, U.S.A.	44 21
770U		
	featured receiver	48 7
	aerials to use	46 7
	dial drive, restringing	48 5
820		
	repairs, various	46 4
	48 27
830		
	830/7, repairs to.....	45 29
	830/9	
	case, different size.....	43 2
	synthesiser, use with	43 2
	Piccolo, use with	43 2
	comparison with AR88 / CR91A	47 22
	drifting.....	47 16
840		
	advert, factory.....	46 31
	Braille set.....	44 17
	dropper resistor, substitute for	46 21
	mains voltage fluctuations.....	48 28
840A		
	a.v.c. problems.....	48 10
840C		
	advert, factory.....	48 20
	fitting of parallel tuned filter for improved reproduction	43 10
	S meter adaptation	47 31
850		
	component values	44 16
	pair in rack, used with teleprinters	45 8
850/4		
	errors in manual.....	48 22
870		
	owned by US member (green knobs sought !)	48 4
	rectifier valve, failure of.....	47 3
	repairs, general	46 19
	restoration.....	47 16
870A		
	reliability & general comments	46 1
880		
	greater recognition deserved	44 4
	restoration notes (F6EFM)	44 15
	880/3	

880	<i>cont 'd</i>		
	brief description	45	22
	manual available.....	45	22
	46	1
	Marconi H.2301, equivalent to.....	46	1
880/2			
	featured receiver	46	5
	picture of	47	9
880/4			
	differences between /2.....	48	21
888			
	calibrator, repairs to	48	11
	faults, various	46	2
888A			
	query as to case without lid	46	21
909A			
	hum, curing.....	46	2
940			
	early models, differences.....	45	3
	46	3
	47	19
	poorer selectivity than 680	43	28
	repairs to, various	48	16
958			
	/7E variant, first to have digital readout.....	46	6
	manuals available, original.....	47	30
	query as to suffix, digital display model	47	17
	success of.....	44	5
1002			
	IC, equivalent for TAA300 sought.....	46	13
	noise, curing	43	24
1650/6			
	on surplus market	45	0
	caution when buying	45	5
	46	1
	47	30
1810			
	Brief details	48	26
1830			
	German version purchased	48	26
1990			
	picture of station.....	45	2
	description of station	45	6
All-World Two			
	advert, factory.....	44	23
	cost, new.....	44	27
	review, Practical & Amateur Wireless (1936)	44	2
All World Six	<i>- see 710</i>		
Atlantic Two			
	description, sold by Harrods.....	45	9

EA12		
featured receiver	44	11
advert, factory	48	20
faults	48	23
price, new	46	19
product detector, problems with	44	13
'S' meter	46	24
.....	47	22
EB35		
hiss, unaffected by volume control	43	27
transistors, replacement	44	9
EB35 II/S		
comparison with EB35 IIS	44	24
EB35 IIS		
comparison with EB35 II/S	44	24
EB36A		
excessive current consumption	43	27
EC10		
advert, factory	48	20
hiss, unaffected by volume control	43	27
noise, reducing in output stages	43	27
overloading	43	31
Radiophile, The, featured in	47	1
resistors and condensers, ageing of	47	2
transistors, replacement	44	9
transistors, substitute, BC212 used in AF output	44	28
EC10 MkII		
fine tuning control	47	17
ECR		
mint example bought (Tor Marthinsen)	47	31
EM34		
brief details	45	4
ERA		
brief mention, vis a vis ERA7	43	30
confirmation of existence of ERA7	45	8
Everyman Four		
brief details	45	1
Homelander		
featured receiver	45	15
brief details	45	1
Homeland Four		
construction booklet available	44	34
Kilodyne Four		
advert, factory (Antarctic expedition)	44	7
advert	45	12
.....	47	18
comments on Antarctic usage (Ted Moore)	44	25
Scientific Short Wave Three		
construction booklet available	44	34
discovery of existence of by Graeme Wormald	43	5

Scientific Three Portable

details, illustration & advert.....	43	22
query as to details.....	43	10

Short Wave Two

constructed by Martin Lindars & Graeme Wormald	45	32
report of set in use, Graeme Wormald	46	25

Sphinx

information about	48	19
restoration of, major	48	16

Transmitter RAFCWR, c.w., crystal controlled

featured model.....	47	12
.....	47	31
building of example, Graeme Wormald	48	36

INDEX TO EDDYSTONE RECEIVERS

	<i>issue</i>	<i>page</i>
31A		
catalogue extract.....	49	9
214 & 215		
brief description	52	6
.....	53	11
358X		
bought at car boot sale.....	51	23
repairs to.....	49	17
valves.....	49	31
440 & 450		
brief description	52	6
.....	53	11
504		
advert.....	53	9
640		
advert.....	53	9
distortion	52	2
modified for 2 metres	53	6
problems with set acquired by member	53	19
query as to handles (or not)	49	27
query as to internal speaker	50	3
659		
identification <i>vis a vis</i> 670.....	49	20
659/670		
hybrid model	51	2
670		
identification <i>vis a vis</i> 659.....	49	20
670A		
condenser problems.....	50	36
680		
transformer rewind	50	29
680X		
featured receiver	53	16
advert.....	52	31
purchased in Cornwall.....	51	22
restoring to original	54	7
700		
featured model.....	49	14
schematic, reference to	51	5
two owned by member	51	30
720		
Yachtsman & EY11 equivalent.....	53	15
730/4		
burning smell, HT tracking.....	50	36
colours.....	51	31
740		
S Meter fitted.....	51	30
750		
a.f. output, loss of.....	53	2
i.f. frequency	51	3
tuning gangs, cleaning.....	52	20
with S meter (?).....	49	27

750 *cont'd*

750/2 differences <i>vis a vis</i> Marconi HR100	49	31
750/2 MIMCO 2232 equivalent	50	39
770		
advert, factory.....	50	35
770R II		
receiving satellites	50	33
used in 2 metre station (Canada)	51	23
770S		
variants	54	12
820		
advert (Strattons) 1955	51	35
repairs.....	53	5
tuning problem	51	4
830		
origins of	54	11
830/4		
purchased in Canada.....	51	23
830/7		
transformer problems	54	7
830/9		
coax fault & replacement.....	49	5
not working	51	5
830/12		
description & Hagenuk E81 equivalent.....	51	31
840A		
i.f. transformer problem.....	52	19
query as to valve bases	51	29
840C		
advert.....	52	31
a.g.c., poor, cured (G3GGL)	51	24
dial illumination	54	28
live case.....	54	3
poor performance at l.f.	52	4
850/4		
error in manual	49	27
repairs to.....	49	16
870		
advert.....	52	15
improving signal reception	49	3
no. of valves (early models)	50	31
870A		
advert.....	52	31
resistors replaced	53	12
880/2		
advert.....	52	31
monitor speaker repairs	49	27
888A		
advert.....	52	31
calibrator	54	4
909		
restoration by member	54	2
930		
featured model.....	51	6
model variants	49	32
930/12	51	3
940		
component failure.....	49	28
gain, low	52	29

940 cont'd

purchased in Scotland (Brian Abrams).....	50	26
.....	52	33
'S' meter problems.....	54	5
used in AFVs.....	51	4
variants.....	54	13
958		
catalogue extract.....	49	9
958/4, Marconi H2310 equivalent.....	54	13
958/5, Mimco Nebula equivalent.....	52	12
960		
advert, Strattons.....	54	23
964		
catalogue extract.....	49	9
990R		
catalogue extract.....	49	9
990S		
production totals.....	54	15
1001		
catalogue extract.....	49	9
1002		
catalogue extract.....	49	9
fault, curing		
rack mounting - not !.....	49	27
1004		
catalogue extract.....	49	9
fault repaired.....	49	3
1650		
brochure (reference to).....	49	21
1830		
advert, factory.....	53	14
info sought as to /ICE suffix.....	54	16
1940		
featured receiver.....	53	9
1990R		
catalogue extract.....	49	9
All World 6		
owned by Tor Marthinsen.....	54	18
All World 8		
featured Wireless World 1936.....	53	23
EA12		
repairs to.....	49	17
cw/ssb mode failure.....	53	20
EB35		
BC212 transistor fitted to f.m. section.....	49	4
catalogue extract.....	49	9
f.m. reinstated.....	49	4
zener diode noise.....	50	33
EB36A		
query as to GPO use.....	51	29
EB37		
featured receiver.....	50	10
ECR		
owned by Tor Marthinsen.....	53	11
EC10		
advert, Strattons.....	54	25
EC10M		
acquired by member.....	54	15

Eddystone 2 Valve receiver		
blueprint	53	3
EM34		
repairs to.....	52	29
Marconi Elettra.....	54	16
Everyman Two		
information sought (Blueprint 950).....	49	31
.....	53	4
Orion 5000		
featured model.....	52	12
5600/2 version.....	52	21
Portable		
query as to	53	13
Yachtsman		
EY11 & 720 equivalent.....	53	15

(General Index Next Page)

INDEX TO EDDYSTONE RECEIVERS

	<i>issue</i>	<i>page</i>
31A		
Eddystone & P.O. versions	57	10
query as to existence of Model 31	58	17
358		
modifications, query as to Royal Navy	57	10
query as to date introduced	59	7
restoration of	55	1
440		
advert for transmitter	55	38
504		
instability problems	58	34
556/B		
solid state vibrator sought .	59	7
above available	60	4
640		
amateur use in 1950	55	35
cooling, improving	59	5
double superhet modified set	55	26
FETs, use of	57	6
MIMCO badged version (not ?)	55	20
ocean voyage, used on (1952)	55	26
serial nos., query as to early	58	18
testimonial, Calcutta	57	34
testimonial, Abu Sueir	59	24
tuning gang cleaning	55	13
valve, repairing	56	4
659		
description	55	20
659B		
testimonial, Tanganyika	59	24
659/670		
testimonial, Invercargill	57	34
testimonial, S.S. Ranheim .	59	24
670		
used in Montreal	55	39
testimonial, British West Indies	57	34
testimonial, M. V. British Bombardier	59	24
testimonial, MV La Pampa	55	39
.....	57	34
670A		
mains switch, faulty	56	5
new valves fitted	59	4
670C/1		
Mimco 2232B	57	9

820		
fault repaired	59.....	6
query as to coverage	56.....	12
830		
featured model.....	55.....	14
colours, query as to.....	58.....	17
common faults.....	55.....	16
filters, crystal.....	56.....	3
government & services usage, query as to	58.....	18
Piccolo	56.....	3
microswitches.....	57.....	11
770, use in conjunction with	60.....	5
840		
20 years in use with member.....	59.....	8
840A		
AF driver stage fault & cure.....	58.....	27
Brimistor & new bulbs	56.....	5
special variant.....	60.....	7
tried out by member	59.....	12
840C		
faulty connection, dropper resistor.....	56.....	5
870		
Antarctic, account of use in (Peter Chisholm).....	59.....	32
advert, Strattons.....	59.....	33
870A		
dropper resistor, replacement by transformer	56.....	5
881		
brief description	57.....	9
888		
improving ssb reception	59.....	13
888A		
repairs to	56.....	30
909		
quest for & acquisition of (Anthony Richards).....	59.....	9
910		
similarities to 830.....	55.....	33
940		
AVC fault, curing.....	58.....	25
in use with G4DTC, Ray Howgego.....	56.....	13
in use with G.E.W. Hewlett.....	56.....	13
repairs to	60.....	38
restoration of, Jeff King, ZL3TNV.....	56.....	18
stenode modification	56.....	12
958		
ratio arm, setting (Simon Robinson).....	56.....	17
scale cursor query (Jim McGowan)	57.....	10
scale cursor cured as a result of above.....	58.....	18

680		
testimonial, Iraq Port Directorate.....	57.....	34
used in Belgian Congo	55.....	39
680X		
variants	57.....	9
700		
in use on RMS Queen Mary.....	55.....	37
query as to <i>vis a vis</i> IMR54	56.....	12
710		
used in Nigeria	55.....	39
730		
corroded solder joints.....	55.....	33
drive system, cleaning.....	56.....	2
i.f.s, aligning.....	60.....	18
testimonial, BBC.....	57.....	34
730/4		
polychromatic brown version.....	56.....	12
resistor failure.....	59.....	25
730/6		
variant	58.....	17
740		
aerial impedance, importance of.....	59.....	6
testimonial, Victoria, Australia	59.....	24
750		
design fault possibility (G3XFE).....	58.....	8
featured model.....	57.....	21
comments, Chris Pettit	57.....	0
faulty audio capacitor	55.....	20
modification reversed.....	59.....	5
review, 'The Radio Amateur', 1952	58.....	9
'S' meter to make.....	57.....	23
testimonial, New York State	55.....	39
testimonial, Toronto	57.....	34
valve holder problem.....	58.....	8
770R		
restoration, major	60.....	9
Turkish version.....	57.....	7
.....	58.....	5
comments by Bill Cooke.....	58.....	33
770R Mk II		
improving performance (Brian Cauthery, VE3DFC).....	59.....	15
shorting plugs	57.....	25
.....	58.....	5
.....	58.....	33
.....	60.....	19
used by RAF & RN	58.....	6
830, use in conjunction with	60.....	5
770S		
variant	57.....	10

990R		
drop testing, factory.....	60.....	37
in service at gliding club ...	55.....	5
1000		
new toggle switches	56.....	5
1650		
featured model.....	58.....	19
designer in EUG	60.....	6
loss of by factory	58.....	2
story of (Chris Pettit) ..	59.....	26
Operation Raleigh, used by	58.....	2
1837		
featured model.....	60.....	13
6200		
continues in production	55.....	35
All World Two		
acquisition & description, G3GGL.....	56.....	27
All World Four		
full description, all variants, accessories etc.....	58.....	37
testimonial, Salisbury, S. Rhodesia.....	59.....	24
used in New Guinea & Solomons, WW II	55.....	39
All World Six		
testimonial, Papua New Guinea	59.....	24
EA12		
caution <i>re</i> diodes	60.....	5
EB35		
batteries, use of PP9	56.....	5
replacing panel bulbs with LEDs	55.....	27
Zener diode & dropper resistor	60.....	20
EB37		
batteries, use of PP9	57.....	3
frequency drift, curing.....	58.....	26
low gain	56.....	2
nicads, use of.....	57.....	2
EC10		
batteries, use of PP9	56.....	5
fine tuning problem	60.....	8
i.f.s cannibalised.....	56.....	16
instability, curing.....	59.....	28
purchased by member.....	59.....	12
QRM, curing (Radio 4)	57.....	4
p.s.u. PCB	60.....	31
replacing panel bulbs with LEDs	55.....	27
restoration (G3XFE).....	60.....	36
selectivity improvements & service notes (J. Duckworth)	57.....	18
switch wafers, loose	56.....	4
transistors, replacing OC171s with BSX29s.....	59.....	28

EC10 Mk II		
static causing transistor failure.....	58.....	16
'S' meter problem	56.....	15
EC10A		
protective diodes	55.....	22
Everyman Short Wave Receiver		
Improved version.....	57.....	12
.....	57.....	13
EY11		
prototype model.....	55.....	22
featured model.....	59.....	22
Kilodyne 4		
advert, Strattons.....	60.....	22
Orion 5000		
notes on development & marketing	59.....	2
Orion 7000 HF radiotelephone		
production ceases	55.....	22
Radiosonde receiver		
featured model.....	56.....	25
Scientific Four		
sold at auction	58.....	33



INDEX TO EDDYSTONE MODELS

	<i>issue</i>	<i>page</i>
All Wave Four		
advert	65	31
development, description and photo.....	65	28
photo	65	1
review, Wireless Magazine, 1931	65	32
All World Four		
reference to Wireless World review	63	14
All World Six		
<i>see 710 model</i>		
All World Eight		
description and photos	64	55
owned by member (Jim Boal)	65	8
R101, military equivalent	64	55
.....	65	16
Stratton & Co, letter from	65	9
Atlantic Two		
acquired in N.Z. (Bryan Marsh)	61	10
featured model	62	14
photo of	62	1
reception, transatlantic, guaranteed.....	64	7
Atlantic Short Wave Two		
'Eddystone specified' construction project	63	36
Atlantic Three		
'Eddystone Specified' construction project.....	64	50
Band Spread All Dry Four		
'Eddystone specified' construction project	66	32
EA12		
non-standard set	64	5
EB35		
acquired at auction, M5POO	66	26
electric shock.....	66	26
fm, curing lack of	63	52
EB35 Mk III		
1982 price.....	62	6
above Incorrect (Bill Cooke).....	6	34
EC10		
acquisition and recommissioning	63	50
drifting	61	39
.....	63	8
i.f. transformers, query as to substitutes	61	39
Toko units	66	4
replacement effected by member (Jim Duckworth)	66	15
production details.....	61	39
'repair', disastrous	62	8
transistors, BSX29 substitute for OC171	61	39
ditto RCA 2N370	64	63
ditto NKT674 and 2N2907, possibility of	64	63
.....	63	8
AFZ11 & AFZ12 substitutes for OC170	63	8
website.....	63	8
ECR		
acquired by member	63	51
Brazil, set discovered and Info sought.....	66	6
EY11 (Yachtsman)		
acquired at Leicester show	63	13
.....	63	18
'Home brew Eddystone'		
built by Roger Bebbington	63	1
.....	63	9
Homeland Four		
advert, Stratton & Co	63	16

	<i>issue</i>	<i>page</i>
Kilodyne Four		
advert, reference to	61	7
photos and acquisition, M5POO	63	34
Orion 5000		
brief production history	65	3
Orion 7000		
brief production history	65	3
Overseas Four		
acquired by member, M5POO (photo - of set not POO!)	66	27
R101		
military version of All World Eight, info required and photo	64	55
Regional One		
first ever Eddystone, 1924	61	6
Scientific Three		
construction manual, reprint of	64	25
Scientific Four		
advert, Harrods	64	19
circuit description	64	18
Scientific Five		
details required	61	11
Short Wave Two		
constructed by member	64	20
Short Wave Three		
adjustment and operation	61	4
circuit	61	5
constructors' handbook, reference to	64	17
Two valve vhf transceiver		
'Eddystone Specified', not production model	62	38
'Tardis'		
multi service f.m. transposer system, brief description	61	2
XE 10 vhf transmitter		
.....	64	3
Yachtsman (720)		
featured model	61	21
advert (factory)	61	1
.....	61	21
in use on yacht	63	18
replica, possibility of building	66	8
358		
advert (Webb's Radio)	61	16
development model found	65	37
i.f.t. repair	64	61
'new' set discovered	66	5
.....	66	10
repairs to	63	14
400		
advert (Webb's Radio)	61	16
440/450 Tx/Rx		
to be recommissioned by member	65	6
640		
acquisition and renovation by member	63	7
advice sought re poor performance	61	33
b.f.o. upgrade	66	6
calibration, jump in, curing	65	34
comments on above, G3GGL	61	34
crystal filter switch	62	9
noise limiter valve, EB34	61	11
tracking, curling	66	4
670A		
electric shock	62	30
670C		
rejuvenation of Marconi 2232A badged version	64	47

	<i>issue</i>	<i>page</i>
680		
acquired by Simon Robinson.....	62	36
control knob variations	62	7
.....	64	63
photo and brief description.....	66	38
wiring, incorrect, early models	62	9
680X		
HMS Narvik, seen on.....	62	31
710		
/B version, non-existent	66	8
vibrator, repair to.....	65	10
Yachtsman developed from	61	21
720		
<i>see Yachtsman</i>		
730		
/1a		
Diplomatic Wireless Service collapsible model	65	12
/4		
circuit modification	64	54
differences compared with 730/10.....	63	35
germanium diodes fitted, query as to.....	63	6
solid state product detector	62	28
pcb for above modification	63	15
/10		
differences compared with 730/4.....	63	35
newly acquired set.....	64	53
750		
C85 fitted to early models.....	62	32
mixer valve	61	7
octal plug missing.....	65	7
twin sets purchased by member.....	66	6
770M		
never produced in volume.....	63	33
770R		
deafness, use of pre-amp.....	61	27
drive cord, use of fishing line.....	61	28
rustling noise, curing.....	65	37
820		
featured model	66	12
performance problems, curing	63	20
photo	66	1
repair and recommissioning	65	6
valve upgrades	61	7
830		
/4		
alignment query	64	17
/7		
comparison with Kenwood R5000	62	7
multiple faults, curing	66	5
/9		
Piccolo filters.....	65	35
.....	66	28
840A		
comparison with 840C.....	64	8
running cooler on 110v.....	61	33
running repairs over 43 years.....	63	52
840C		
comparison with 840A	64	8
repairs	65	25
850/4		
aerials for use with	61	34
low gain, curing	61	8

	<i>issue</i>	<i>page</i>
870		
elusive fault.....	66	7
prototype found ?	66	8
870A		
fault finding.....	63	19
in everyday use.....	62	8
recomissioning.....	65	17
888		
cogwheel repair.....	63	15
crystal calibrator repair.....	65	7
output transformer problems	61	10
product detector.....	63	15
recomissioning.....	62	31
whistles, curing	61	7
940		
fault finding.....	62	40
resistor replacement	64	63
valve seating problem	63	35
990R		
1982 price.....	62	6
deafness, use of pre-amp.....	61	27
Met. Office, acquired by.....	61	40
publicity at launch	62	34
reception	61	27
repair, muting switch	62	11
Short Wave Magazine review	64	21
1002		
bfo – not!.....	63	13
1004		
high noise level	61	11
Marconi Sentinel, Redifon, Hagenuk & ITT variants	61	11
1570		
owned by Chris Pettitt	64	3
1705		
vhf/fm broadcast transmitter	62	3
1650		
pros and cons, set owned by Michael O'Beirne	61	29
response to above by designer, Roger Sutton	61	31
use with submarines	66	3
1837		
/1 variant, u.s.b. only	61	7
common capacitor problem	64	7
notes and faultfinding (Gary Donovan)	62	4
1838		
comparison with FRG 100	62	7
6100		
brief mention, Chris Pettitt	63	3
6200		
brief mention, Chris Pettitt	63	3

INDEX TO EDDYSTONE MODELS

	<i>issue</i>	<i>page</i>
31A		
used in recent comparison tests	71.....	40
40A		
modifications enabling ssb usage	67.....	9
scale plate photocopy	67.....	3
358		
comparison with 400	71.....	16
restoration notes	71.....	11
Royal Navy, in use with	71.....	44
214/215		
advert, Stratton & Co	70.....	49
development of early vhf equipment	70.....	48
358X		
mystery RAF photo	70.....	53
400		
comparison with 358	71.....	16
i.f. frequency	72.....	15
400B		
analysis of (Peter Lankshear)	71.....	37
comments on, Pat Hawker, G3VA	72.....	47
description	71.....	36
504		
advert, factory	67.....	24
introduced in 1946	68.....	4
640		
acquisition and restoration, Brian Cauthery	70.....	32
ditto, Ted Moore	72.....	10
heat reduction	72.....	19
i.f. breakthrough	67.....	10
revalving	67.....	7
valve and resistor failure	70.....	16
659		
brief notes	67.....	7
670A		
magic eye restored to life	72.....	14
680		
review submitted by G0OGN	67.....	21
test report, Wireless World 1949	67.....	22
680X		
acquisition and repair by Graeme Wormald	70.....	54
700		
built for Boardroom by Stan Carney	70.....	30
710		
communal listening model	68.....	4
730/1a		
restoration of Diplomatic Wireless Service model, Roger Bebbington	70.....	4

Lighthouse Index, Issues 67-72

	issue	page
730/4		
co-ax connectors available	70.....	43
shock resistant mounts	67.....	30
740		
unused ex Civil Defence model saved from skip	72.....	12
750		
i.f. frequency explained, Graeme Wormald	72.....	42
restoration, Roger Bebbington	72.....	42
770R II		
in daily use	71.....	14
820		
cased version	67.....	5
condenser omitted from circuit	67.....	5
transformer failure	72.....	16
830		
fingerplates available	72.....	2
830/4		
renovation, Joel Balogh	70.....	23
830/5		
frequency jumps, curing.....	70.....	20
830/9		
servicing and bandwidth conversion (Jim Duckworth)	67.....	37
840A		
query as to i.f. transformers	70.....	20
rustling cured	72.....	17
840C		
magic eye, problems resolved	67.....	4
renovation, Graeme Wormald	70.....	22
870		
deafness, possible causes.....	67.....	10
870A		
acquired by Ted Moore.....	70.....	17
isolation transformer installed	71.....	13
880		
local oscillator comments.....	71.....	8
888		
avc problems	67.....	6
900		
c.w. transmitter, mobile, prototype	67.....	12
940		
alignment using sweep generator	72.....	35
comparison with Realistic DX394	70.....	17
deafness cured	72.....	13
history of one receiver, Peter Lankshear	70.....	6
restoration by Ted Moore	71.....	12
repair notes, by Roger Bebbington	68.....	39
940HF		
model discovered by Ted Moore	71.....	11
958		
faults, suggestions as to curing	67.....	31

Lighthouse Index, Issues 67-72

	issue	page
958/7E		
featured model	67	17
1002		
restoration, Ted Moore	70	37
tuning problems	70	18
1610		
brief description	71	34
1650		
converting ex-GCHQ models (Geoff Steadman)	72	6
1806/2		
handset amplifier, query as to	67	2
All World Six – see 710		
All World Eight		
speaker	67	31
Amateur Bands Two		
full description and circuit ('Eddystone Specified')	68	16
description	71	42
review	68	17
Atlantic Two		
not the first Eddystone receiver ?	71	24
EA12		
AVC problems	67	32
repairs, Ted Moore	71	13
EB35		
different circuitry as compared with Mk III	67	21
HRH Prince Charles, fitted to car	67	21
modifications corrected	72	16
silicon devices to replace germanium transistors	68	35
Toko i.f. coils as substitutes	68	34
EB35 Mk III		
acquired & got working	67	6
different circuitry as compared with Mk II	67	21
negative earth, warning as to	68	26
EB37		
restoration, by Chris Morgan	68	35
silicon devices to replace germanium transistors	68	35
Toko i.f. coils as substitutes	68	34
EC10		
Mimco 6689 equivalent	71	14
modifications corrected	72	16
modifications, Tom Toth	72	44
output transformer replaced	70	14
substitute IFTs, care as to	67	8
silicon devices to replace germanium transistors	68	35
Toko i.f. coils as substitutes	68	34
EC10A		
different i.f. frequencies	67	8
Eddystone 3 Valve Receiver		
first Eddystone receiver ?	71	24
advert	71	26

Lighthouse Index, Issues 67-72

	<i>issue</i>	<i>page</i>
IMR 54		
advert, IMRC	70.....	31
story of, and R.M.S. Queen Mary	70.....	28
Statesman - see <i>EB35 Mk III</i>		
Super Six		
description and restoration	71.....	15
Twin		
acquired by Simon Robinson, description & photos	70.....	50
Two		
data sheet found, 1926 model	70.....	11
XE10		
brief description	68.....	3
XE15		
stereo exciter	68.....	3

PLEASE TURN OVER FOR GENERAL INDEX

***By carefully prising the staples on the next page
you may remove this index to keep with the relevant issues.***

INDEX TO EDDYSTONE MODELS

	<i>issue</i>	<i>page</i>
358		
advert, Webbs Radio (1942)	73	20
400		
Home office MF network.....	73	29
Wireless World, write-up in (S400).....	74	12
400B		
comments on usage of, Pat Hawker	73	22
ditto, Graeme Wormald	73	23
query as to Air Sea Rescue use	73	6
440/450		
D Day, used in invasion.....	73	25
Lancashire Police, used by	77	8
S147, Admiralty nomenclature for 440/450	76	15
504		
story of one receiver, Peter le Quesne.....	74	4
556		
fuse, lack of	78	14
mains transformer replacement.....	78	14
pot. replacement.....	78	14
second receiver found (Ted Moore)	78	16
640		
advert, 1948 (Webb's Radio).....	76	55
BFO improvement	74	19
prices, new	75	9
repairs to.....	75	10
rf stage, cascade conversion.....	76	18
6V6 valve	74	10
670		
condenser, leaky	73	9
testimonial	75	15
670A		
frequency coverage compared with Marconi variants.....	76	16
heater chain problem.....	74	15
low gain cured	74	10
670C		
acquired by Graeme Wormald (at last!)	76	6
acquired by Ted Moore.....	75	7
audio fault cured, Graeme Wormald	77	11
fault on one band.....	74	20
680		
advert, Stratton & Co Ltd (1949)	77	6
..... drift cured.....	74	15
owned from new, Jim Daniels (NZ)	77	5
680X		
aerial fault cured, Graeme Wormald	77	11
.....	77	31
hum, curing.....	73	10
740		
fault, factory, cured	76	7
hum, curing.....	74	17
in use many years	74	15

Lighthouse Index Issues 73-78

750	hum, curing	76	17
770CE	vlf to uhf receive unit.....	76	17
770R	aerial links.....	74	34
	BBC, used by.....	75	11
	Cumbrian News Group, used by	77	19
	performance, improving.....	78	12
	repairs to Mk II.....	75	6
	rustling cured	74	9
770U	coil contact problem, 770U (Brian Cauthery)	77	40
	hard wired mains, NZ	78	6
820	dry joint	73	8
	valve problem cured	74	16
830	calibrator switch, changing to toggle	77	26
	78	5
	fault cured, Brian Cauthery.....	76	22
	ditto, Graeme Wormald	77	10
	HT, lack of, curing.....	76	17
	knobs, mismatching.....	73	11
	restoration		
 Chris Morgan	77	28
 Joe LeKostaj.....	78	19
	sales brochure reprint.....	77	21
	/4 model, query as to Canadian usage.....	78	21
840	BFO, intermittent, curing	74	18
	description	75	15
840C	acquired by Ted Moore.....	75	8
	refurbishing (Peter Beardsmore)	74	28
870	scale reversed on these models.....	75	10
870A	receiving ssb signals	74	11
	rejuvenated by Ted Moore	76	11
880	acquired by Ted Moore, with picture	76	9
	product detector fault.....	76	16
888	crystal calibrator		
	repair.....	73	10
	tuning.....	74	16
	fuse blowing, cured.....	74	18
930/1	acquired by Simon Robinson	76	44
940	advert (Webb's Radio, 1962).....	78	24
	cascode problems resolved.....	78	42
	coil former fault found	73	4
	improvements suggested (G8POO).....	75	40
	comments on foregoing improvements		
 G8POO.....	78	24
 Peter Lankshear	76	32
 Ross Paton	78	6
	instability problems	77	42

940 (contd.)		
..... in-depth article with graphs (Graeme Wormald)	78	27
comments on, Terry Parker (Eddystone Chief of Test)	78	34
ranges not working	77	14
resistor fault	74	14
taken to school (Ted Moore)	74	8
958		
bulbs, query as to voltage	77	20
990R		
picture on index	75	centre
1002		
front panel replacement	77	14
1990R/2		
acquired by Ted Moore, with picture	76	10
fault, cutting out, curing	76	14
6200		
available at discount	73	24
EB35		
audio hiss, curing	77	33
bulbs, query as to voltage	77	20
noise, output stage	76	16
power supply, mains, noisy	76	16
restored to life	75	9
EB35 Mk II		
audio hiss, curing	77	33
restored to life	75	5
EB36		
acquired by Ted Moore	75	5
audio hiss, curing	77	33
noisy set cured	74	9
EB36A		
differences between this & EB36	75	38
EC10		
audio hiss, curing	77	33
bulbs, query as to voltage	77	20
circuit diagram errata	74	8
cutting out, curing	76	15
Isle of Arran, in use on	78	16
noise, output stage	76	16
power supply, mains, noisy	76	16
printed circuit board repairs	76	13
transistor faults	73	6
transistor upgrades to modern types	73	6
wrong psu supplied	73	5
EC10 Diplomat		
brief details	75	29
ECR		
acquired by Ted Moore	77	12
Everyman		
copy brochure	78	8
All Wave Four		
well travelled, in use many years (Amy O'Neil)	75	22
All World Two		
adapting for 10 metres	76	13
Atlantic Three		
details of	78	33
Everyman		
comments by Tor Marthinsen	77	36

Lighthouse Index Issues 73-78

IMR54		
	pictures of, shipboard	78 40
Kilodyne Four		
	advert, Stratton & Co Ltd, 1931	74 24
	full description, Wireless Magazine 1932	74 25
	comments by Tor Marthinsen	77 36
Orion		
	in use on EUG net	73 24
	spares, query as to (Simon Robinson)	78 25
	transceiver available at discount	73 24
Quadradyne		
	comments by Tor Marthinsen	77 36
R101		
	military set, full description of, & circuit	74 36
Scientific Four		
	full description, circuit, pictures	76 25
	comments by Tor Marthinsen	77 36
Scientific Three		
	details of	78 32
Sphinx		
	comments by Tor Marthinsen	77 36
Three		
	description of	78 32
S147		
	440/450 equivalent, used by R.N.	76 15
WS57		
	440/450 equivalent, used by Army	77 9

INDEX TO EDDYSTONE MODELS

	<i>issue</i>	<i>page</i>
All Wave Four		
Used in India, rejuvenated after 50 years.....	79	6
All World Two		
Kit review, Wireless World	79	24
Discussion regarding (Tor Marthinsen) & picture	79	36
All World Eight		
Discussion on, Tor Marthinsen	80	22
Amateur Bands two		
Discussion regarding (Tor Marthinsen)	79	36
Atlantic Two		
Discussion regarding (Tor Marthinsen) & picture	79	36
EA12		
Full description and pictures	81	10
EB35		
Acquired for restoration.....	80	32
Restoration continues	81	37
Ditto	82	15
Prince Charles, owned by	82	15
Tuning cord reversed	79	12
Wavechange switch problems	84	35
EB35 Mk II		
Output transistor replacement	79	17
EC10 Mk II		
Goat Fell, used portable.....	80	33
Mimco equivalent	79	15
ECR		
At NVCF, picture of	79	39
Discussion regarding (Tor Marthinsen)	80	22
Eddystone Two		
Discussion regarding (Tor Marthinsen)	79	36
Eddystone Short Wave		
Discussion regarding (Tor Marthinsen)	79	36
EM34		
Mimco equivalent	79	15
Empire Two		
Description, circuit & pictures	81	28
Discussion regarding (Tor Marthinsen)	79	36
ERA 7		
Discussion regarding (Tor Marthinsen)	80	22
Homeland Four		
Factory advert	83	25
Kilodyne Four		
Description, circuit, pictures	82	31
To be built ?		
Ted Moore	83	19
Graeme Wormald	82	46
Orion		
Sold to Egypt.....	83	5
Sold on Ebay + picture.....	84	5
Scientific Two		
Advert for	80	12
Discussion regarding (Tor Marthinsen) & picture	79	36

Lighthouse Index Issues 79-84

Sentinel – see 1004

Short Wave two

Discussion regarding (Tor Marthinsen)	79	36
Full description	80	13

Sphinx

Discussion regarding (Tor Marthinsen)	80	22
---	----	----

Super Six

Discussion regarding (Tor Marthinsen)	80	20
---	----	----

Transmitters

215, info in blueprint register	80	28
Stereo 500	84	21

358X

Used at Admiralty Signal Establishment.....	82	6
---	----	---

40A

Used by Ted Moore	82	18
-------------------------	----	----

400

Advert, Webb's Radio (1941).....	82	23
----------------------------------	----	----

440/450

Used in LCTs, D Day	80	29
---------------------------	----	----

640

Fault cured, dry joint	80	29
Another dry joint.....	80	31
Phasing control improvement	84	20

640A

Blueprint found, info. Sought	83	21
-------------------------------------	----	----

659/670

Discussion as to identity (Ted Moore)	80	31
---	----	----

670

Merchant Navy, popular with	82	39
Valve heater short.....	83	18

670A

Mimco equivalent	79	15
------------------------	----	----

670C

Merchant Navy, popular with	82	39
Mimco equivalent	79	12

680

Fault cured (Peter Lankshear)	83	6
-------------------------------------	----	---

680X

Microphony	82	44
Renovation of (Roger Bebbington)	79	23
Scale plate cleaning.....	79	23

840A

Importance of aerial link.....	79	12
--------------------------------	----	----

730

Scale plate, cleaning.....	79	23
Fuses	84	36
Power transformer disaster.....	84	42

750

Doublet aerial described in Marconi HR100 manual	79	32
Pulley replacement query	79	16
Scale plate cleaning.....	79	23

760

New model discovered ?.....	82	13
.....	82	46

770R

Aerial, correct type vital.....	84	16
Valves in wrong places	79	12

770U

Full description and pictures	83	9
-------------------------------------	----	---

Lighthouse Index Issues 79-84

820	H.T. circuit repair.....	79	16
830	AF gain problems cured.....	80	361
	Knobs cracking.....	80	5
	Power supply problem	83	14
	RCAF modification labels.....	80	36
	RCMP model.....	80	36
	Restored to working order (John Gillespie)	81	18
	Usage in Canadian Govt. service (David W. Whiting).....	79	29
	Sideband fault resolved	82	30
	Spares kit	80	5
840C	A.M., used on net.....	83	33
	Magic Eye repairs	80	26
	Valve holder problem	82	15
870	Full specifications.....	84	30
	IF core problem	83	19
870A	Models acquired (Ted Moore).....	79	15
	Restoration (Roger Bebbington).....	82	10
880/2	Restoration of.....	82	11
	List of faults, etc.	82	19
888A	Co-ax problems.....	83	20
	Drifting	79	41
	Possible solutions	80	37
	Advert	84	27
	84	29
	Restoration (Ted Moore).....	82	12
	Testimonial (Herb Bartlett, G5QA).....	84	29
910/1	Marconi cross reference to HR101	79	15
940	Drift & heating problems	79	34
	Origins of	79	35
940/1	Variant with crystal controlled channels added	79	14
958	Hagenuk & Marconi equivalents	79	15
1570	Poor sets advertised, acquired (Ted Moore)	81	39
1004	Hagenuk equivalent	79	15
	Description & picture	80	43
1650	Supplied to STC	81	4
1940/1	Info. sought	83	21
	Sent to Marconi for evaluation	79	15
1990R	Tuner damaged by static ?	82	17
	Used on MILAIR frequencies.....	79	17

INDEX TO EDDYSTONE MODELS

	<i>issue</i>	<i>page</i>
31A		
on eBay	89	18
40A		
on eBay	88	24
used on EUG net	88	18
215		
used by RAF & brief details	88	17
440		
quality components used	85	7
in amateur use, postwar, 4 metre band	85	10
on eBay	86	13
358		
advert (Webb's Radio)	86	36
fault cured	88	20
HMS Collingwood, aboard	86	10
included in Wireless for the Warrior	89	36
RAF usage proved	87	30
504		
on eBay	87	12
.....	90	17
556		
comments on (Ted Moore)	89	28
resistors gone high	86	22
640		
obituary (b. 1948, d. 2004)	88	46
repairs to (Barry Jackson)	86	42
659 / 670		
power supply details	90	30
sold on eBay	86	39
.....	88	25
seized bearings	88	20
670A		
power supply details	90	31
vernier scraping dial	89	29
670C		
acquisition & planned restoration (Ted Moore)	90	28
power supply details	90	31
680X		
faulty consignment to India	87	9
in use in South Africa (Barry Jackson)	85	31
on eBay	90	17
720 (Yachtsman)		
in Jersey museum	89	19
730/4		
acquired bt Ted Moore	85	23
CCF, used by	89	6
crystal calibrator problem	85	19
included in Wireless for the Warrior	89	36
in use on EUG net	88	12
good points	88	12
740		
S687 psu	88	20
750		
acquired by David Fletcher, G3TVM	86	28
resistor in output stage – not !	90	25


770R	HMS Collingwood, aboard	86	10
830/4	mains transformer burn-out	90	10
	acquisition & restoration by Brian Cauthery, VE3DFC	90	10
830/7	restoration (Graham Gosling)	88	28
840	Braille model on eBay	86	26
	power supply details	90	30
840A	thermistor problem	86	21
	power supply details	90	31
840C	on eBay	86	26
	90	17
	power supply details	90	31
870 / 870A	drifting cured	90	24
	eliminates QRM	85	21
	modified, with mains transformer	88	59
	on eBay	86	26
	86	31
	86	39
	90	16
	power supply details	90	32
	variations	90	27
888 / 888A	audio output – complex problem resolved (G3GGL)	90	36
	external difference between 888 & 888A	87	11
	in use in South Africa (Barry Jackson)	85	31
	on eBay	87	11
	stability problems, new	89	46
909	acquired from Sweden	89	7
	power supply details	90	32
930	included in Wireless for the Warrior	89	36
940	acquired by David Fletcher, G3TVM	86	28
	information & specifications	85	12
	on eBay	86	26
	88	23
	oxidation on 'phone jack	86	22
958/1	Post Office, 50 sets acquired (1971)	85	43
	restoration (Graham Gosling)	88	28
960	acquired by Ted Moore, restoration begun	86	28
	on eBay	89	9
	restoration continued	88	14
	90	22
964/7	acquired by Ted Moore	85	23
	used for monitoring, North Sea oil platform	86	21
	use of Telefunken panadaptor	86	40

990R		
microphony	89	22
tuning gear problems	89	27
using portable	88	21
variations	90	27
1002		
HMS Collingwood, aboard	86	10
problems with, Ted Moore	86	17
1560R/2		
query as to model designation & help wanted	85	22
sold as Marconi Marlin	86	19
1990R		
acquired by Ted Moore	85	23
HMS Collingwood, aboard	86	10
problems resolved (Alan Robinson)	87	32
All World Two		
owned by Davis Fletcher, G3TVM	86	28
All World Eight		
in military use	89	26
Atlantic Two		
sold at auction	86	39
EA12		
on eBay	86	26
.....	86	31
.....	88	24
.....	90	15
EB35		
acquired by Ted Moore	87	29
psu plug polarity	85	20
damaged cores & transformers	89	25
variations	90	27
EB37		
acquired by Ted Moore	87	29
EC10 / EC10 MkII		
acquired by Ted Moore, new variant ?	87	28
dial lamp module	90	44
EUG net, used on	88	18
HMS Collingwood, aboard	86	10
on eBay	88	24
as new model	90	15
Portugal	89	6
psu plug polarity	65	20
variations	90	27
EM34		
acquired at NVCF	85	8
Orion 5000		
acquired & recommissioning by Ted Moore	85	27
.....	86	15
in use	88	19
on yacht 'Esselle'	90	25
on Eddystone Radio QSL card	88	4
R101C		
included in Wireless for the Warrior	89	36
Scientific Two		
discovered by member	90	26
Ultra Short Wave Receiver		
on offer	87	17
WS 57		
included in Wireless for the Warrior	89	36

INDEX

'Lighthouse' issues 91-96 incl.

June 2005 to April 2006



Model EA12, the ultimate Hambander 1964-69

Our grateful thanks to Anthony Richards, GW4RYK,
for compiling this index in record time.

INDEX TO EDDYSTONE MODELS

	<i>issue</i>	<i>page</i>
358		
unwanted emissions	92	32
440		
acquired by Ted Moore.....	96	39
450		
acquired by Ted Moore.....	96	39
504		
acquired (Ted Moore), with strange valve	94	47
mains switch problem	95	20
556		
brief details and picture.....	96	37
640		
drive cord joy	95	19
presented to RSGB.....	93	7
640A		
blueprint found	94	49
670A		
670/670A hybrid.....	93	16
drive cord comments	95	19
magic eye improvements.....	96	22
Marconi variants	96	36
670C		
magic eye improvements.....	96	22
Marconi variants	96	36
700		
history	92	16
730/1A		
on eBay	93	26
730/4		
on eBay	93	26
used by CCF	93	10
750		
/2 version	95	18
favourite model (Terry Parker) details, test results.....	94	21
on eBay	93	26
output stage valve.....	91	6
testimonial	94	28
vibrator psu	94	27
760		
listed by factory.....	94	49
770R		
on eBay	92	19
770S		
brief description and picture.....	96	36
770U		
on eBay	92	19
830		
meter end-stopping.....	94	51
tuning lock	91	12
/8 models released	96	36
/9 models released	96	36

Lighthouse Index, Issues 91-96

840C			
	advertisement	95	40
		95	41
	on eBay	94	14
	mains wrongly wired	95	22
	stability	95	19
870			
	valves used, comments on (Ross Paton)	91	7
	19AQ5 valve, discussion (Peter Lankshear)	92	36
870A			
	on eBay	93	26
	valve failure	94	44
		94	48
880			
	used by GCHQ	92	33
	on eBay	94	13
	tuning mechanism problems.....	91	5
888			
	brochure reprint	96	18
	Bill Cooke, comments.....	96	19
888A			
	on eBay	94	15
940			
	advertisement	95	40
		95	41
	development history.....	95	39
	on eBay	94	13
	refurbishment (Graham Sutton)	92	13
950			
	valved radio to cope with EMP	93	32
958			
	assessment, School of Signals (1977)	94	6
	maritime radio, used by	94	9
	sold on eBay	91	21
990R			
	drive cord comments	95	19
	fault finding (Geoff Harris).....	93	38
	layout differences.....	95	23
	on eBay	94	14
	scale calibration	94	28
990S			
	drive cord comments	95	19
	mystery variant (Louis Muelstee).....	96	24
	on eBay	94	14
	scale calibration	94	28
1001			
	sold on eBay	91	20
1002			
	lack of AVC, cured	94	44
	on eBay	95	28
	on eBay	95	29
1004			
	on eBay	95	28
1529			
	RTTY terminal.....	96	34

Lighthouse Index, Issues 91-96

1560		
ROM missing	93	19
1650		
sold on eBay	91	19
1706 transmitter		
sold on eBay	91	19
2232A (Marconi)		
capacitor failure	94	44
2245A (Marconi)		
670A equivalent acquired (ted Moore)	94	48
2273A (Marconi)		
fault cured	93	18
frequency coverage	96	36
3873A (Marconi)		
P.A. built in	96	36
6100		
joys & pitfalls of ownership (Dave Jones, MW1DUJ)	91	25
All World Two		
advert	92	30
sold on eBay & pictures of	92	18
All World Six		
advertisement	95	24
.....	95	25
Atlantic Two		
comments and picture	94	39
Crystal Set		
picture of	92	5
ditto plus comments	94	37
EA12		
frequency coverage & stations audible	95	16
meter end-stopping	94	51
sold on eBay	91	20
.....	94	15
EB35		
brief description	96	39
EB35A		
differences from standard model	96	37
EC10		
on eBay	92	19
.....	93	25
.....	95	29
resistor failure, cured	94	44
scale markings, comments on (Terry Parker)	94	28
.....	95	23
EC10M		
equivalent of Marconi Seaguide, full details	94	9
Homelander		
used by Mt. Everest Expedition, plus details & pictures	95	36
Homeland Four		
picture of, at Colchester rally	93	24
Kilodyne Four		
restoration	96	10
KT66		
built for RAF & RN reservists	96	54
Portable Three		
comments	94	38
Queen Mary - see 700		

Lighthouse Index, Issues 91-96

Regional One	93	5
ditto and comments	94	40
Scientific Four		
comments and picture	94	39
Scientific Five		
comments and picture	94	40
Scientific Portable Three		
comments and picture	94	41
Scientific Short Wave Three		
comments and picture	94	40
Scientific Two		
owned by member	93	17
Scientific Screened Grid H.F. Short Wave Three		
New model discovered resembling above (Percy Mistry)	91	8
Short-Wave		
comments and picture	94	39
first Eddystone	96	14
Wireless World extract	96	15
Super Six		
omitted from QRG, but evidence of	96	44
Three		
comments and picture	94	38
Twin		
picture of & on display	93	24
comments and picture	94	38
sold on eBay & picture of	92	17
Two		
comments and picture	94	38
Unknown model		
see <i>Scientific Screened Grid H.F. Short Wave Three</i>		