


3-pole



60°

3	48 	20A 32A	M10H . M20 .	x x x x x x x x	x ¹⁾ - - -	. U3 . U3
	64 	32A 50A	N20 . N33F .	x - x - x x x -	x x x -	. U3 . U3
	88 	63A 90A 115A	N40 . N61 . N80 .	x - x - x - x - x - x -	x - x - - -	. U3 . U3 . U3
	132 	150A 250A	N100 . N200 .	x - x - x - x -	- - - -	. U3 . U3



+007

