

2-pole	T1 T4 T2 T5 L1 L2	60°	2	48 	20A 32A	M10H . M20 .	x x x x x ¹⁾ - x x x x - -	. U2 . U2	0 1 2 +007 OFF 1 2
				64 	32A 50A	N20 . N33F .	x - x - x x x x x - x -	. U2 . U2	
				88 	63A 90A 115A	N40 . N61 . N80 .	x - x - x - x - x - x - x - x -	. U2 . U2 . U2	
				132 	150A 250A	N100 . N200 .	x - x - - - x - x - - -	. U2 . U2	