

001568

METER ADJ WAS ADS
~~DISCONNECTED PEG~~
MISSING
METER FSD IN "ON"
MODE

001569


MISSING MICROPH
~~NO METER ADJ PEG~~
PEGS FSD IN "ON"
MODE,
METER

001586

METER ADJ PEG MISSING
PEGS FSD IN "ON"
MODE

001572

METER ADJ PEG MISSING
MISSING SCREW BACK OF METER
PEGS ON FSD IN "ON"
MODE.



1,3 ME4002

2 ME0414

4 ME0414 BC238

5 ~~BC~~ J232 MEF101 E232

3 BC173