

Drawings

2051 01 to 06 , 11 to 20 2052 01 to 07 2053 01 to 03 Portable Miniature Meter

> Unit: mm (approx. inch)





	Name
①	Case
2	Rear Cover
3	Cover
4	Mounting Screw
(5)	Zero Adjustor
6	Scale Plate
7	Pointer
8	Knob
9	Rubber Leg

For Zero-Center meter, pointer is at center.

Unless otherwise specified here, all dimensions should be applied tolerance of

 $\pm 3\% (\pm 0.3$ mm in case less than 10 mm.).

WEIGHT APPROX.

kg

